


序号	报告编号	发布日期	结论	影像资料
41	GX-B1495/20-2-231246~231254	2023. 9. 7	所检项目合格	
42	GX-B1495/20-2-231255~231265	2023. 9. 7	所检项目合格	

43	GX-B1495/20-2-231266~231272	2023. 9. 7	所检项目合格	
44	GX-B1495/20-2-231273~231281	2023. 9. 7	所检项目合格	

45	GX-B1495/20-2-231282~231290	2023. 9. 7	所检项目合格	
46	GX-B1495/20-2-231291~231301	2023. 9. 7	所检项目合格	

47	GX-B1495/20-2-231302~231306	2023. 9. 7	所检项目合格	
48	GX-B1495/20-2-231307~231311	2023. 9. 7	所检项目合格	

49	GX-B1495/20-2-231324~231327	2023. 9. 7	所检项目合格	
50	GX-B1495/20-2-231312~231317	2023. 9. 7	所检项目合格	

51	GX-B1495/20-2-231318~231323	2023. 9. 7	所检项目合格	 <p>2023/07/17</p>
52	GX-B1495/20-2-231328~231332	2023. 9. 7	所检项目合格	 <p>2023/07/17</p>

53	GX-B1495/20-2-231342~231347	2023. 9. 7	所检项目合格	 <p>2023/07/13</p>
54	GX-B1495/20-2-231333~231341	2023. 9. 7	所检项目合格	 <p>2023/07/13</p>

55	GX-B1321/20-2-23466~23469	2023. 9. 7	所检项目合格	 <p>2023/07/14</p>
56	GX-B1321/20-2-23470~23473	2023. 9. 7	所检项目合格	 <p>2023/07/14</p>

57	GX-B1321/20-2-23474~23483	2023. 9. 7	所检项目合格	
58	GX-B1321/20-2-23484~23486	2023. 9. 7	所检项目合格	

59	GX-B1321/20-2-23487~23489	2023. 9. 7	所检项目合格	
60	GX-B1321/20-2-23490~23495	2023. 9. 7	所检项目合格	

61	GX-B1312/20-2-23275~23276	2023. 9. 7	所检项目合格	
62	GX-B1312/20-2-23277~23283	2023. 9. 7	所检项目合格	

63	GX-B1312/20-2-23284~23287	2023. 9. 7	所检项目合格	
64	GX-B1312/20-2-23288~23291	2023. 9. 7	所检项目合格	

65	GX-B1312/20-2-23292~23293	2023. 9. 7	所检项目合格	
66	GX-B1312/20-2-23294~23300	2023. 9. 7	所检项目合格	

67	GX-B1314/21-2-23015~23016	2023. 9. 7	所检项目合格	
68	GX-B1328/20-2-23136	2023. 9. 7	所检项目合格	

69	GX-B1328/20-2-23137	2023. 9. 7	所检项目合格	
70	GX-B1312/20-2-23438~23446	2023/9/7	本次共检电力变压器9台， 9台电力变压器所检项目合格。	

71	GX-B1312/20-2-23421~23437	2023/9/7	本次共检电力变压器 17台，17台电力变压器所 检项目合格。	
72	GX-B1323/21-2-23128~23131	2023. 9. 7	所检项目合格	

73	GX-B1323/21-2-23132~23135	2023. 9. 7	所检项目合格	
74	GX-B1323/21-2-23136~23137	2023. 9. 7	所检项目合格	

75	GX-B1495/20-2-231223~231226	2023. 9. 8	所检项目合格	
76	GX-B1495/20-2-231231~231235	2023. 9. 8	所检项目合格	

77	GX-B1495/20-2-231227~231230	2023. 9. 8	所检项目合格	 <p>2023/07/12</p>
78	GX-B1495/20-2-231236~231245	2023. 9. 8	所检项目合格	 <p>2023/07/13</p>

79	GX-B1310/21-2-23179	2023. 9. 5	符合标准要求。	
80	GX-B1310/21-2-23180	2023. 9. 5	符合标准要求。	

81	GX-B1310/21-2-23181	2023. 9. 5	符合标准要求。	
82	GX-B1428/21-2-23182	2023. 9. 5	无缺陷迹痕显示。	

83	GX-B1428/21-2-23183	2023. 9. 5	无缺陷迹痕显示。	
84	GX-B1310/21-2-23184	2023. 9. 6	符合标准要求。	

85	GX-B1310/21-2-23185	2023. 9. 6	符合标准要求。	
86	GX-B1310/21-2-23186	2023. 9. 6	符合标准要求。	

87	GX-B1598/21-2-23073	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为0.47%，小于5%为正常。	
88	GX-B1598/21-2-23074	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为0.75%，小于5%为正常。	

89	GX-B1598/21-2-23075	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为0.21%，小于5%为正常。			
90	GX-B1598/21-2-23076	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为0.33%，小于5%为正常。			

91	GX-B1598/21-2-23077	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为1.03%，小于5%为正常。			
92	GX-B1598/21-2-23078	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。			

93	GX-B1598/21-2-23079	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为0.88%，小于5%为正常。	 <p>2023/08/07</p>
94	GX-B1598/21-2-23080	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为0.64%，小于5%为正常。	 <p>2023/08/07</p>

95	GX-B1598/21-2-23081	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为0.58%，小于5%为正常。	
96	GX-B1598/21-2-23082	2023. 9. 10	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常。	

97	GX-B1328/20-2-23143	2023. 9. 11	检绝缘手套2只，2只所检项目	
98	GX-B1328/20-2-23144	2023. 9. 11	检绝缘鞋2只，2只所检项目	

99	GX-B1328/20-2-23145	2023. 9. 11	检绝缘手套2只，2只所检项目	
100	GX-B1328/20-2-23146	2023. 9. 11	检绝缘鞋2只，2只所检项目	

101	GX-B1328/20-2-23147	2023. 9. 11	检绝缘手套2只，2只所检项目	
102	GX-B1328/20-2-23148	2023. 9. 11	检绝缘鞋2只，2只所检项目	

103	GX-B1328/20-2-23149	2023. 9. 11	检绝缘手套2只，2只所检项目	 <p>2023/09/23</p>
104	GX-B1328/20-2-23150	2023. 9. 11	检绝缘鞋2只，2只所检项目	 <p>2023/09/23</p>

105	GX-B1312/20-2-23447~23450	2023. 9. 11	所检项目合格	
106	GX-B1312/20-2-23451~23453	2023. 9. 11	所检项目合格	

107	GX-B1312/20-2-23454~23463	2023. 9. 11	所检项目合格	 <p>2023/07/22</p>
-----	---------------------------	-------------	--------	---