

序号	报告编号	发布日期	结论	影像资料
38	GX-B1598/24-6-25001替代GX-B1598/24-6-24175	2025/1/20	实测钢丝绳有效截面积损失百分比最大为1.24%，小于5%为正常。 。	 <p>2024 12 02</p>
39	GX-B1598/24-6-25002替代GX-B1598/24-6-24176	2025/1/20	实测钢丝绳有效截面积损失百分比最大为1.31%，小于5%为正常。 。	 <p>2024 12 02</p>

40	GX-B1598/24-6-25003替代GX-B1598/24-6-24177	2025/1/20	实测钢丝绳有效截面积损失百分比最大为1.21%，小于5%为正常。	
41	GX-B1598/24-6-25004替代GX-B1598/24-6-24178	2025/1/20	实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。	
42	GX-B1598/24-6-25005替代GX-B1598/24-6-24179	2025/1/20	实测钢丝绳有效截面积损失百分比最大为1.37%，小于5%为正常。	

43	GX-B1598/24-6-25006替代GX-B1598/24-6-24180	2025/1/20	实测钢丝绳有效截面积损失百分比最大为1.41%，小于5%为正常。		
44	GX-B1303/21-6-25001	2025/1/20	综合判定：合格。		
45	GX-B1310/21-6-25001	2025/1/21	符合标准要求		

46	GX-B1310/21-6-25002	2025/1/21	符合标准要求		
47	GX-B1310/21-6-25003	2025/1/21	符合标准要求		
48	GX-B1310/21-6-25004	2025/1/21	符合标准要求		

49	GX-B1427/21-6-25001	2025/1/21	符合标准要求		
50	GX-B1427/21-6-25002	2025/1/21	符合标准要求		
51	GX-B1522/20-6-25001	2025/1/23	所检项目合格。		

52	GX-B1522/20-6-25002	2025/1/23	所检项目合格。	
53	GX-B1522/20-6-25003	2025/1/23	所检项目合格。	