

序号	报告编号	发布日期	结论	影像资料
287	GX-B1522/20-Y-23028	2023年3月24日	所检项目合格。	
288	GX-B1522/20-Y-23029	2023年3月24日	所检项目合格。	

289	GX-B1521/20-Y-23032	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	
290	GX-B1539/22-Y-23009	2023年3月24日	所检项目合格。	
291	GX-B1423/20-Y-23583	2023年3月24日	综合判定：合格	

292	GX-B1423/20-Y-23584	2023年3月24日	综合判定：合格	
293	GX-B1423/20-Y-23585	2023年3月24日	综合判定：合格	

294	GX-B1423/20-Y-23586	2023年3月24日	综合判定：合格	
295	GX-B1423/20-Y-23587	2023年3月24日	综合判定：合格	

296	GX-B1423/20-Y-23588	2023年3月24日	综合判定：合格	
297	GX-B1423/20-Y-23589	2023年3月24日	综合判定：合格	

298	GX-B1423/20-Y-23590	2023年3月24日	综合判定：合格	
299	GX-B1423/20-Y-23591	2023年3月24日	综合判定：合格	

300	GX-B1423/20-Y-23592	2023年3月24日	综合判定：合格	
301	GX-B1423/20-Y-23593	2023年3月24日	综合判定：合格	

302	GX-B1423/20-Y-23594	2023年3月24日	综合判定：合格	
303	GX-B1423/20-Y-23595	2023年3月24日	综合判定：合格	

304	GX-B1423/20-Y-23596	2023年3月24日	综合判定：合格	
305	GX-B1423/20-Y-23597	2023年3月24日	综合判定：合格	

306	GX-B1423/20-Y-23598	2023年3月24日	综合判定：合格	
307	GX-B1423/20-Y-23599	2023年3月24日	综合判定：合格	

308	GX-B1423/20-Y-23600	2023年3月24日	综合判定：合格	
309	GX-B1423/20-Y-23601	2023年3月24日	综合判定：合格	

310	GX-B1423/20-Y-23602	2023年3月24日	综合判定：合格	
311	GX-B1521/20-Y-23033	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	

312	GX-B1521/20-Y-23034	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	
313	GX-B1521/20-Y-23035	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	

314	GX-B1521/20-Y-23036	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	
315	GX-B1521/20-Y-23037	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	

316	GX-B1521/20-Y-23038	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	
317	GX-B1556/22-Y-23001	2023年3月24日	所检项目合格。	

318	GX-B1556/22-Y-23002	2023年3月24日	所检项目合格。	
319	GX-B1521/20-Y-23045	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	

320	GX-B1521/20-Y-23046	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	
321	GX-B1557/22-Y-23001	2023年3月24日	所检项目合格。	

322	GX-B1557/22-Y-23002	2023年3月24日	所检项目合格。	
323	GX-B1539/22-Y-23014	2023年3月24日	所检项目合格。	

324	GX-B1539/22-Y-23015	2023年3月24日	所检项目合格。	
325	GX-B1556/22-Y-23003	2023年3月24日	所检项目合格。	

326	GX-B1521/20-Y-23042	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	
327	GX-B1521/20-Y-23043	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	

328	GX-B1521/20-Y-23044	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
329	GX-B1423/20-Y-23553	2023年3月24日	综合判定：合格	

330	GX-B1423/20-Y-23554	2023年3月24日	综合判定：合格	
331	GX-B1423/20-Y-23555	2023年3月24日	综合判定：合格	

332	GX-B1423/20-Y-23556	2023年3月24日	综合判定：合格	
333	GX-B1423/20-Y-23557	2023年3月24日	综合判定：合格	

334	GX-B1423/20-Y-23558	2023年3月24日	综合判定：合格	 A yellow dump truck with license plate 1-2-6 is parked on a dirt surface. Two workers in safety gear stand in front of it. The date 2023/3/2 is visible in the bottom right corner of the photo.
335	GX-B1423/20-Y-23559	2023年3月24日	综合判定：合格	 A yellow dump truck with license plate 1-2-7 is parked on a dirt surface. Two workers in safety gear stand in front of it. The date 2023/3/2 is visible in the bottom right corner of the photo.

336	GX-B1423/20-Y-23560	2023年3月24日	综合判定：合格	 A yellow dump truck with the number 8 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/3/2 is visible in the bottom right corner.
337	GX-B1423/20-Y-23561	2023年3月24日	综合判定：合格	 A yellow dump truck with the number 9 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/3/2 is visible in the bottom right corner.

338	GX-B1423/20-Y-23562	2023年3月24日	综合判定：合格	 A yellow dump truck with the license plate 130 is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the text '同力重工' (Tongli Heavy Industry) on its side. A date stamp '2023/3/2' is visible in the bottom right corner of the image.
339	GX-B1423/20-Y-23563	2023年3月24日	综合判定：合格	 A yellow dump truck with the license plate 131 is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the text '同力重工' (Tongli Heavy Industry) on its side. A date stamp '2023/3/2' is visible in the bottom right corner of the image.

340	GX-B1423/20-Y-23564	2023年3月24日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has the number '132' on its side. A yellow timestamp '2023/3/2' is visible in the bottom right corner of the image.
341	GX-B1423/20-Y-23565	2023年3月24日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has the number '132' on its side. A yellow timestamp '2023/3/2' is visible in the bottom right corner of the image.

342	GX-B1423/20-Y-23566	2023年3月24日	综合判定：合格	
343	GX-B1423/20-Y-23567	2023年3月24日	综合判定：合格	

344	GX-B1423/20-Y-23568	2023年3月24日	综合判定：合格	
345	GX-B1423/20-Y-23569	2023年3月24日	综合判定：合格	

346	GX-B1423/20-Y-23570	2023年3月24日	综合判定：合格	
347	GX-B1423/20-Y-23571	2023年3月24日	综合判定：合格	

348	GX-B1423/20-Y-23572	2023年3月24日	综合判定：合格	
349	GX-B1423/20-Y-23573	2023年3月24日	综合判定：合格	

350	GX-B1423/20-Y-23574	2023年3月24日	综合判定：合格	 A yellow dump truck with '同力重工' (Tongli Heavy Industry) written on its side. Two workers in safety gear stand in front of it. A yellow timestamp '2023/3/3' is in the bottom right corner.
351	GX-B1423/20-Y-23575	2023年3月24日	综合判定：合格	 A yellow dump truck with 'TONLY' written on its side. Two workers in safety gear stand in front of it. A yellow timestamp '2023/3/3' is in the bottom right corner.

352	GX-B1423/20-Y-23576	2023年3月24日	综合判定：合格	 A yellow dump truck with '同力重工' (Tongli Heavy Industry) and '4' on its side. Two workers in safety gear stand in front of it on a dirt surface. A yellow timestamp '2023/3/3' is in the bottom right corner.
353	GX-B1423/20-Y-23577	2023年3月24日	综合判定：合格	 A yellow dump truck with '同力重工' (Tongli Heavy Industry) and '4 5' on its side. Two workers in safety gear stand in front of it on a dirt surface. A yellow timestamp '2023/3/3' is in the bottom right corner.

354	GX-B1423/20-Y-23578	2023年3月24日	综合判定：合格	
355	GX-B1423/20-Y-23579	2023年3月24日	综合判定：合格	

356	GX-B1423/20-Y-23580	2023年3月24日	综合判定：合格	
357	GX-B1423/20-Y-23581	2023年3月24日	综合判定：合格	

358	GX-B1423/20-Y-23582	2023年3月24日	综合判定：合格	
359	GX-B1423/20-Y-23538	2023年3月24日	综合判定：合格。	

360	GX-B1423/20-Y-23539	2023年3月24日	综合判定：合格。	
361	GX-B1423/20-Y-23540	2023年3月24日	综合判定：合格。	

362	GX-B1423/20-Y-23541	2023年3月24日	综合判定：合格。	
363	GX-B1423/20-Y-23542	2023年3月24日	综合判定：合格。	

364	GX-B1423/20-Y-23543	2023年3月24日	综合判定：合格。	
365	GX-B1423/20-Y-23544	2023年3月24日	综合判定：合格。	

366	GX-B1423/20-Y-23545	2023年3月24日	综合判定：合格。	 A yellow dump truck with its bed raised, parked on a dirt surface. Two workers in orange safety gear stand in front of the truck. The truck has '同力重工' (Tongli Heavy Industry) and the number '8' on its side. A yellow date stamp '2023/2/28' is in the bottom right corner.
367	GX-B1423/20-Y-23546	2023年3月24日	综合判定：合格。	 A yellow dump truck with its bed raised, parked on a dirt surface. Two workers in orange safety gear stand in front of the truck. The truck has '同力重工' (Tongli Heavy Industry) and the number '3' on its side. A yellow date stamp '2023/2/28' is in the bottom right corner.

368	GX-B1423/20-Y-23547	2023年3月24日	综合判定：合格。	
369	GX-B1423/20-Y-23548	2023年3月24日	综合判定：合格。	

370	GX-B1423/20-Y-23549	2023年3月24日	综合判定：合格。	
371	GX-B1423/20-Y-23550	2023年3月24日	综合判定：合格。	

372	GX-B1423/20-Y-23551	2023年3月24日	综合判定：合格。	 A yellow dump truck with license plate 857 is parked on a dirt surface. Two workers in safety gear stand in front of it. The date 2023/2/28 is visible in the bottom right corner of the photo.
373	GX-B1423/20-Y-23552	2023年3月24日	综合判定：合格。	 A yellow dump truck with license plate 859 is parked on a dirt surface. Two workers in safety gear stand in front of it. The date 2023/2/28 is visible in the bottom right corner of the photo.

374	GX-B1521/20-Y-23047	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	
375	GX-B1521/20-Y-23048	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	

376	GX-B1521/20-Y-23049	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	
377	GX-B1521/20-Y-23050	2023年3月24日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》， 所检项目合格。	

378	GX-B1539/22-Y-23016	2023年3月24日	所检项目合格。	
379	GX-B1539/22-Y-23017	2023年3月24日	所检项目合格。	

380	GX-B1539/22-Y-23018	2023年3月24日	所检项目合格。	
381	GX-B1539/22-Y-23019	2023年3月24日	所检项目合格。	

382	GX-B1539/22-Y-23020	2023年3月24日	所检项目合格。	
383	GX-B1522/20-Y-23033	2023年3月25日	所检项目合格。	

384	GX-B1522/20-Y-23034	2023年3月25日	所检项目合格。	
385	GX-B1557/22-Y-23003	2023年3月25日	所检项目合格。	

386	GX-B1423/20-Y-231454	2023年3月25日	综合判定：合格	
387	GX-B1423/20-Y-231455	2023年3月25日	综合判定：合格	

388	GX-B1423/20-Y-231456	2023年3月25日	综合判定：合格	 A yellow dump truck with the license plate number 12 is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The date 2023/3/13 is visible in the bottom right corner of the photo.
389	GX-B1423/20-Y-231457	2023年3月25日	综合判定：合格	 A yellow dump truck with the license plate number 05 is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The date 2023/3/13 is visible in the bottom right corner of the photo.

390	GX-B1423/20-Y-231458	2023年3月25日	综合判定：合格	
391	GX-B1423/20-Y-231459	2023年3月25日	综合判定：合格	

392	GX-B1423/20-Y-231460	2023年3月25日	综合判定：合格	 A yellow dump truck with license plate 12 is parked on a dirt surface. Two people are standing next to it. The date 2023/3/13 is visible in the bottom right corner.
393	GX-B1423/20-Y-231461	2023年3月25日	综合判定：合格	 A yellow dump truck with license plate 07 is parked on a dirt surface. Two people are standing next to it. The date 2023/3/13 is visible in the bottom right corner.

394	GX-B1423/20-Y-231462	2023年3月25日	综合判定：合格	 A yellow dump truck with license plate 08 is parked on a dirt surface. Two workers in safety gear stand in front of it. The date 2023/3/13 is visible in the bottom right corner of the photo.
395	GX-B1423/20-Y-231463	2023年3月25日	综合判定：合格	 A yellow dump truck with license plate 09 is parked on a dirt surface. Two workers in safety gear stand in front of it. The date 2023/3/13 is visible in the bottom right corner of the photo.

396	GX-B1423/20-Y-231464	2023年3月25日	综合判定：合格	
397	GX-B1423/20-Y-231465	2023年3月25日	综合判定：合格	

398	GX-B1423/20-Y-231466	2023年3月25日	综合判定：合格	
399	GX-B1423/20-Y-231467	2023年3月25日	综合判定：合格	

400	GX-B1423/20-Y-231468	2023年3月25日	综合判定：合格	
401	GX-B1423/20-Y-231469	2023年3月25日	综合判定：合格	

402	GX-B1423/20-Y-231470	2023年3月25日	综合判定：合格	 A yellow dump truck with the number 38 on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/3/13' is in the bottom right corner.
403	GX-B1423/20-Y-231471	2023年3月25日	综合判定：合格	 A yellow dump truck with the number 39 on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/3/13' is in the bottom right corner.

404	GX-B1423/20-Y-231472	2023年3月25日	综合判定：合格	
405	GX-B1423/20-Y-231473	2023年3月25日	综合判定：合格	

406	GX-B1423/20-Y-231474	2023年3月25日	综合判定：合格	
407	GX-B1423/20-Y-231475	2023年3月25日	综合判定：合格	

408	GX-B1423/20-Y-231476	2023年3月25日	综合判定：合格	
409	GX-B1423/20-Y-231477	2023年3月25日	综合判定：合格	

410	GX-B1423/20-Y-231478	2023年3月25日	综合判定：合格	 A yellow Volvo 50 dump truck is parked on a dirt surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. The truck has "VOLVO 50" written on its side. A yellow timestamp "2023/3/14" is visible in the bottom right corner of the photo.
411	GX-B1423/20-Y-231479	2023年3月25日	综合判定：合格	 A yellow Volvo 50 dump truck is parked on a dirt surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. The truck has "VOLVO 50" written on its side. A yellow timestamp "2023/3/14" is visible in the bottom right corner of the photo.

412	GX-B1423/20-Y-231480	2023年3月25日	综合判定：合格	
413	GX-B1423/20-Y-231481	2023年3月25日	综合判定：合格	

414	GX-B1423/20-Y-231482	2023年3月25日	综合判定：合格	
415	GX-B1423/20-Y-231483	2023年3月25日	综合判定：合格	

416	GX-B1423/20-Y-231484	2023年3月25日	综合判定：合格	
417	GX-B1423/20-Y-231485	2023年3月25日	综合判定：合格	

418	GX-B1423/20-Y-231486	2023年3月25日	综合判定：合格	
419	GX-B1423/20-Y-231487	2023年3月25日	综合判定：合格	

420	GX-B1423/20-Y-231488	2023年3月25日	综合判定：合格	
421	GX-B1423/20-Y-231489	2023年3月25日	综合判定：合格	

422	GX-B1423/20-Y-231490	2023年3月25日	综合判定：合格	
423	GX-B1423/20-Y-231491	2023年3月25日	综合判定：合格	

424	GX-B1423/20-Y-231492	2023年3月25日	综合判定：合格	
425	GX-B1423/20-Y-231493	2023年3月25日	综合判定：合格	

426	GX-B1423/20-Y-231494	2023年3月25日	综合判定：合格	
427	GX-B1423/20-Y-231495	2023年3月25日	综合判定：合格	

428	GX-B1423/20-Y-231496	2023年3月25日	综合判定：合格	A photograph of a large, dark-colored dump truck parked on a paved surface. Two people are standing in front of the truck. The person on the left is wearing a red hard hat, a high-visibility yellow vest over a grey long-sleeved shirt, and grey pants. The person on the right is wearing a dark blue jacket and blue jeans. The truck has a license plate with the number '75' and a date stamp '2023/3/14' in the bottom right corner. A small inset image at the top of the photo shows a person's legs and feet.
-----	----------------------	------------	---------	---