

序号	报告编号	发布日期	结论	影像资料
683	GX-B1423/20-Y-231277	2023年3月25日	综合判定：合格	
684	GX-B1423/20-Y-231278	2023年3月25日	综合判定：合格	

685	GX-B1423/20-Y-231279	2023年3月25日	综合判定：合格	 <p>2023/3/8</p>
686	GX-B1423/20-Y-231280	2023年3月25日	综合判定：合格	 <p>2023/3/8</p>

687	GX-B1423/20-Y-231281	2023年3月25日	综合判定：合格	 <p>A photograph showing a worker wearing a red hard hat and a white uniform, seated in the driver's seat of a vehicle. The worker is looking down at the controls, which include a steering wheel and various levers. The interior of the vehicle is visible, and there is a yellow timestamp '2023/3/8' in the bottom right corner of the image.</p>
688	GX-B1423/20-Y-231282	2023年3月25日	综合判定：合格	 <p>A photograph of a yellow dump truck parked in a snowy field. The truck has the number '079' on its side. Two people are standing near the front of the truck. The sky is overcast, and the ground is covered in snow. There is a yellow timestamp '2023/3/8' in the bottom right corner of the image.</p>

689	GX-B1423/20-Y-231283	2023年3月25日	综合判定：合格	
690	GX-B1423/20-Y-231284	2023年3月25日	综合判定：合格	

691	GX-B1423/20-Y-231285	2023年3月25日	综合判定：合格	
692	GX-B1423/20-Y-231286	2023年3月25日	综合判定：合格	

693	GX-B1423/20-Y-231287	2023年3月25日	综合判定：合格	 A yellow dump truck is parked on a snowy surface. Two people are standing near the front of the truck. The truck has "ZAL" on the side. A yellow date stamp "2023/3/8" is in the bottom right corner.
694	GX-B1423/20-Y-231288	2023年3月25日	综合判定：合格	 A yellow dump truck is parked on a snowy surface. Two people are standing near the front of the truck. The truck has "079" on the side. A yellow date stamp "2023/3/8" is in the bottom right corner.

695	GX-B1423/20-Y-231289	2023年3月25日	综合判定：合格	
696	GX-B1423/20-Y-231290	2023年3月25日	综合判定：合格	

697	GX-B1423/20-Y-231291	2023年3月25日	综合判定：合格	
698	GX-B1423/20-Y-231292	2023年3月25日	综合判定：合格	

699	GX-B1423/20-Y-231293	2023年3月25日	综合判定：合格	
700	GX-B1423/20-Y-231294	2023年3月25日	综合判定：合格	

701	GX-B1423/20-Y-231295	2023年3月25日	综合判定：合格	
702	GX-B1423/20-Y-231296	2023年3月25日	综合判定：合格	

703	GX-B1423/20-Y-231297	2023年3月25日	综合判定：合格	 A yellow dump truck with the model number MT996L and the number 090 on its side. Two people are standing in front of the truck. A yellow timestamp '2023/3/9' is visible in the bottom right corner of the photo.
704	GX-B1423/20-Y-231298	2023年3月25日	综合判定：合格	 A yellow dump truck with the model number MT996L and the number 090 on its side. Two people are standing in front of the truck. A yellow timestamp '2023/3/9' is visible in the bottom right corner of the photo.

705	GX-B1423/20-Y-231299	2023年3月25日	综合判定：合格	
706	GX-B1423/20-Y-231300	2023年3月25日	综合判定：合格	

707	GX-B1423/20-Y-231301	2023年3月25日	综合判定：合格	
708	GX-B1323/21-Y-23004~23011	2023年3月26日	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。	

709	GX-B1323/21-Y-23015~23022	2023年3月26日	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。	
710	GX-B1323/21-Y-23023~23030	2023年3月26日	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。	

711	GX-B1323/21-Y-23031~23038	2023年3月26日	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格。	
712	GX-B1323/21-Y-23039~23053	2023年3月26日	本次共检三相交流电动机15台，15台三相交流电动机所检项目合格。	

713	GX-B1323/21-Y-23054	2023年3月26日	所检项目合格。	
714	GX-B1323/21-Y-23055~23058	2023年3月26日	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	

715	GX-B1323/21-Y-23059~23060	2023年3月26日	本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。	
716	GX-B1323/21-Y-23061~23070	2023年3月26日	本次共检三相交流电动机10台，10台三相交流电动机所检项目合格。	

717	GX-B1323/21-Y-23071~23073	2023年3月26日	本次共检三相交流电动机3台，3台三相交流电动机所检项目合格。	
718	GX-B1323/21-Y-23074~23088	2023年3月26日	本次共检三相交流电动机15台，15台三相交流电动机所检项目合格。	

719	GX-B1323/21-Y-23089~23100	2023年3月26日	本次共检三相交流电动机12台，12台三相交流电动机所检项目合格。	 <p>2023/3/1</p>
720	GX-B1323/21-Y-23101~23112	2023年3月26日	本次共检三相交流电动机12台，12台三相交流电动机所检项目合格。	 <p>2023/3/2</p>

721	GX-B1323/21-Y-23113~23119	2023年3月26日	本次共检三相交流电动机7台，7台三相交流电动机所检项目合格。	
722	GX-B1323/21-Y-23120~23130	2023年3月26日	本次共检三相交流电动机11台，11台三相交流电动机所检项目合格。	

723	GX-B1323/21-Y-23131~23134	2023年3月26日	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	
724	GX-B1323/21-Y-23135~23138	2023年3月26日	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	

725	GX-B1323/21-Y-23139~23144	2023年3月26日	本次共检三相交流电动机6台，6台三相交流电动机所检项目合格。	 <p>2023/3/26</p>
726	GX-B1423/20-Y-23744	2023年3月27日	综合判定：合格	 <p>2023/3/19</p>

727	GX-B1423/20-Y-23745	2023年3月27日	综合判定：合格	
728	GX-B1423/20-Y-23746	2023年3月27日	综合判定：合格	

729	GX-B1423/20-Y-23747	2023年3月27日	综合判定：合格	
730	GX-B1423/20-Y-23748	2023年3月27日	综合判定：合格	

731	GX-B1423/20-Y-23749	2023年3月27日	综合判定：合格	 A yellow dump truck with the license plate M-1017 is parked on a dirt surface. Two workers are standing next to it: one in a yellow safety vest and another in a grey uniform holding a clipboard. The date 2023/3/19 is visible in the bottom right corner of the photo.
732	GX-B1423/20-Y-23750	2023年3月27日	综合判定：合格	 A yellow dump truck with the license plate M-1029 is parked on a dirt surface. Two workers are standing next to it: one in a yellow safety vest and another in a grey uniform holding a clipboard. The date 2023/3/19 is visible in the bottom right corner of the photo.

733	GX-B1423/20-Y-23751	2023年3月27日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers are standing in front of it. One worker is wearing a blue uniform and a red hard hat, while the other is wearing a white uniform and a black hard hat. The truck has the number 'M-166' on its side and '166' on the front of the dump body. A yellow timestamp '2023/3/19' is visible in the bottom right corner of the photo.
734	GX-B1423/20-Y-23752	2023年3月27日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers are standing in front of it. One worker is wearing a blue uniform and a yellow hard hat, while the other is wearing a white uniform and a black hard hat. The truck has the number 'M-166' on its side and '166' on the front of the dump body. A yellow timestamp '2023/3/19' is visible in the bottom right corner of the photo.

735	GX-B1423/20-Y-23753	2023年3月27日	综合判定：合格	 A yellow TORLY M-1003 dump truck is parked on a dirt surface. Two workers are standing in front of the truck. One worker is wearing a blue and yellow high-visibility uniform and a yellow hard hat. The other worker is wearing a tan uniform and a black face mask. The truck has 'TORLY' and 'M-1003' written on its side. A yellow timestamp '2023/3/19' is visible in the bottom right corner of the photo.
736	GX-B1423/20-Y-23754	2023年3月27日	综合判定：合格	 A yellow TORLY M-1003 dump truck is parked on a dirt surface. Two workers are standing in front of the truck. One worker is wearing a blue and yellow high-visibility uniform and a yellow hard hat. The other worker is wearing a tan uniform and a black face mask. The truck has 'TORLY' and 'M-1003' written on its side. A yellow timestamp '2023/3/19' is visible in the bottom right corner of the photo.

737	GX-B1423/20-Y-23755	2023年3月27日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has 'M-1023' on its side. A date stamp '2023/3/19' is visible in the bottom right corner of the photo.
738	GX-B1423/20-Y-23756	2023年3月27日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has 'M-1003' on its side. A date stamp '2023/3/19' is visible in the bottom right corner of the photo.

739	GX-B1423/20-Y-23757	2023年3月27日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. Two workers are standing in front of it. One worker is wearing a blue jacket and a yellow hard hat, while the other is wearing a grey jacket and a black hat. The truck has 'TONLY' written on the side and a license plate that reads '桂A-11111'. A yellow timestamp '2023/3/19' is visible in the bottom right corner of the photo.
740	GX-B1423/20-Y-23758	2023年3月27日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. Two workers are standing in front of it. One worker is wearing a blue jacket and a yellow hard hat, while the other is wearing a grey jacket and a black hat. The truck has 'TONLY' written on the side and a license plate that reads '桂A-11111'. A yellow timestamp '2023/3/19' is visible in the bottom right corner of the photo.

741	GX-B1423/20-Y-23759	2023年3月27日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers are standing next to it. One worker is wearing a blue safety vest and a yellow hard hat, while the other is wearing a grey jacket and a black cap. The truck has '同力重工' (Tongli Heavy Industry) written on its side. A date stamp '2023/3/19' is visible in the bottom right corner of the photo.
742	GX-B1423/20-Y-23760	2023年3月27日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers are standing next to it. One worker is wearing a grey jacket and a yellow hard hat, while the other is wearing a grey jacket and a black cap. The truck has '同力重工' (Tongli Heavy Industry) written on its side. A date stamp '2023/3/19' is visible in the bottom right corner of the photo.