


序号	报告编号	发布日期	结论	影像资料
37	GX-B1568/22-B-230070~230071	2023. 3. 16	所检项目合格	
38	GX-B1568/22-B-230051~230053	2023. 3. 16	所检项目合格	
39	GX-B1603/22-B- 230012~230013	2023. 3. 16	所检项目合格	

40	GX-B1603/22-B- 230010~230011	2023. 3. 16	所检项目合格	
41	GX-B1542/21-B- 23064~23076	2023. 3. 15	所检项目合格	
42	GX-B1542/21-B- 23080~23098	2023. 3. 15	所检项目合格	

43	GX-B1601/22-B- 230055~230059	2023. 3. 16	所检项目合格	
44	GX-B1601/22-B- 230060~230066	2023. 3. 16	所检项目合格	
45	GX-B1372/22-B- 230141	2023. 3. 16	所检项目合格	

46	GX-B1372/22-B- 230142~230146	2023. 3. 16	所检项目合格	
47	GX-B1372/22-B- 230147	2023. 3. 16	所检项目合格	
48	GX-B1540/20-B- 230263~230277	2023. 3. 17	所检项目合格	

49	GX-B1592/21-B- 23018~23019	2023. 3. 17	所检项目合格	 <p>2023.3.17</p>
50	GX-B1474/22-B- 23037~23040	2023. 3. 17	所检项目合格	 <p>2023.3.17</p>
51	GX-B1474/22-B- 23019~23028	2023. 3. 17	所检项目合格	 <p>2023.3.17</p>

52	GX-B1474/22-B- 23029~23036	2023. 3. 17	所检项目合格	
53	GX-B1474/22-B- 23001~23002	2023. 3. 17	所检项目合格	
54	GX-B1540/20-B- 230278~230292	2023. 3. 17	所检项目合格	

55	GX-B1540/20-B- 230293~230297	2023. 3. 16	所检项目合格	
56	GX-B1592/21-B- 23016~23017	2023. 3. 16	所检项目合格	
57	GX-B1374/22-B- 230053~230056	2023. 3. 16	所检项目合格	

58	GX-B1373/21-B- 23056~23066	2023. 3. 16	所检项目合格	
59	GX-B1373/21-B- 23045~23049	2023. 3. 16	所检项目合格	
60	GX-B1474/22-B- 23011~23018	2023. 3. 17	所检项目合格	

61	GX-B1474/22-B- 23003~23010	2023. 3. 17	所检项目合格	
62	GX-B1540/20-B- 230248~230262	2023. 3. 17	所检项目合格	
63	GX-B1540/20-B- 230238~230247	2023. 3. 17	所检项目合格	

64	GX-B1374/22-B- 230045~230052	2023. 3. 17	所检项目合格	 A photograph showing two workers in a laboratory or workshop. One worker is leaning over a table, focused on a piece of equipment. Another worker stands nearby, observing. Both are wearing light-colored jackets and face masks. A date stamp '2023.2.12' is visible in the bottom right corner of the photo.
65	GX-B1373/21-B- 23050~23055	2023. 3. 17	所检项目合格	 A photograph showing a worker operating a piece of industrial machinery. In the foreground, another worker wearing a face mask and glasses is looking towards the camera. The date stamp '2023.3.2' is visible in the bottom right corner of the photo.
66	GX-B1328/20-B-23006	2023. 3. 20	所检项目合格	 A photograph showing a worker in a red safety vest and helmet working on a large piece of equipment in a room. The room has a tiled floor and some other equipment visible. The date stamp '2023.3.6' is visible in the bottom right corner of the photo.

67	GX-B1328/20-B-23007	2023. 3. 20	所检项目合格	
68	GX-B1602/22-B-23007~23008	2023. 3. 22	所检项目合格	
69	GX-B1601/22-B-230075~230077	2023. 3. 22	所检项目合格	

70	GX-B1601/22-B-230071~230074	2023. 3. 22	所检项目合格	
71	GX-B1410/22-B-23001~23006	2023. 3. 23	所检项目合格	
72	GX-B1409/22-B-23001	2023. 3. 23	所检项目合格	

73	GX-B1410/22-B-23007~23009	2023. 3. 23	所检项目合格	 A photograph showing two workers in grey uniforms with a logo on the back, standing in a laboratory. They are looking at a piece of equipment. A date stamp '2023.3.10' is visible in the bottom right corner of the image.
74	GX-B1412/22-B-23003	2023. 3. 23	所检项目合格	 A photograph showing two workers in grey uniforms in a laboratory. One worker is standing near a piece of equipment, and the other is partially visible. A date stamp '2023.3.23' is visible in the bottom right corner of the image.
75	GX-B1592/21-B-23021~23026	2023. 3. 23	所检项目合格	 A photograph showing two workers in grey uniforms in a laboratory. One worker is leaning over a piece of equipment, and the other is standing nearby. A date stamp '2023.3.23' is visible in the bottom right corner of the image.

76	GX-B1592/21-B-23020	2023. 3. 23	所检项目合格	
77	GX-B1411/22-B-23003	2023. 3. 23	所检项目合格	
78	GX-B1373/21-B- 23086	2023. 3. 24	所检项目合格	

79	GX-B1374/22-B- 230097	2023. 3. 24	所检项目合格	
80	GX-B1540/20-B- 230456	2023. 3. 24	所检项目合格	
81	GX-B1601/22-B-230078	2023. 3. 24	所检项目合格	

82	GX-B1475/22-B- 230029~230030	2023. 3. 24	所检项目合格	
83	GX-B1372/22-B- 230202~230205	2023. 3. 24	所检项目合格	