


序号	报告编号	发布日期	结论	影像资料
39	GX-B1377/22-F-23208	2023. 5. 12	所检项目合格	 A photograph showing two individuals in a laboratory or industrial setting. One person, wearing a grey lab coat and glasses, is operating a piece of equipment with a red interior. Another person, wearing a grey lab coat and a blue face mask, stands nearby. The equipment is on a table, and there are other lab items visible in the background.
40	GX-B1378/22-F-23119~F-23122	2023. 5. 15	所检项目合格	 A photograph showing a person in a grey lab coat working at a workstation. The workstation includes a computer monitor, a keyboard, and various pieces of equipment on a green table. The person is looking at the monitor. The background shows a window with yellow curtains.

41	GX-B1377/22-F-23143	2023. 5. 15	所检项目合格	
42	GX-B1377/22-F-23144	2023. 5. 15	所检项目合格	

43	GX-B1377/22-F-23145	2023. 5. 15	所检项目合格	
44	GX-B1377/22-F-23190	2023. 5. 15	所检项目合格	


45	GX-B1377/22-F-23191	2023. 5. 15	所检项目合格	
46	GX-B1377/22-F-23192	2023. 5. 15	所检项目合格	

47	GX-B1377/22-F-23193	2023. 5. 15	所检项目合格	
48	GX-B1377/22-F-23194	2023. 5. 15	所检项目合格	

49	GX-B1377/22-F-23195	2023. 5. 15	所检项目合格	
50	GX-B1377/22-F-23196	2023. 5. 15	所检项目合格	

51	GX-B1377/22-F-23197	2023. 5. 15	所检项目合格	 <p>2023.5.12</p>
52	GX-B1377/22-F-23198	2023. 5. 15	所检项目合格	 <p>2023.5.12</p>

53	GX-B1377/22-F-23199	2023. 5. 15	所检项目合格	
54	GX-B1377/22-F-23200	2023. 5. 15	所检项目合格	

55	GX-B1489/21-F-23033	2023. 5. 15	所检项目合格	
56	GX-B1377/22-F-23146	2023. 5. 15	所检项目合格	

57	GX-B1377/22-F-23147	2023. 5. 15	所检项目合格	
58	GX-B1377/22-F-23148	2023. 5. 15	所检项目合格	


59	GX-B1377/22-F-23149	2023. 5. 15	所检项目合格	
60	GX-B1377/22-F-23150	2023. 5. 15	所检项目合格	

61	GX-B1377/22-F-23156	2023. 5. 15	所检项目合格	
62	GX-B1377/22-F-23157	2023. 5. 15	所检项目合格	


63	GX-B1377/22-F-23158	2023. 5. 15	所检项目合格	
64	GX-B1377/22-F-23159	2023. 5. 15	所检项目合格	



65	GX-B1377/22-F-23160	2023. 5. 15	所检项目合格	
66	GX-B1378/22-F-23130	2023. 5. 15	所检项目合格	


67	GX-B1378/22-F-23131	2023. 5. 16	所检项目合格	
68	GX-B1377/22-F-23161	2023. 5. 15	所检项目合格	


69	GX-B1377/22-F-23162	2023. 5. 15	所检项目合格	
70	GX-B1378/22-F-23125~F-23127	2023. 5. 15	所检项目合格	

71	GX-B1378/22-F-23128	2023. 5. 15	所检项目合格	
72	GX-B1378/22-F-23129	2023. 5. 15	所检项目合格	

73	GX-B1378/22-F-23123	2023. 5. 15	所检项目合格	 A photograph showing two laboratory technicians in white lab coats and masks working at a laboratory bench. They are positioned in front of a biosafety cabinet. The bench is cluttered with various pieces of laboratory equipment, including a green instrument, a water bottle, and some papers. A date stamp '2023/5/7' is visible in the bottom right corner of the image.
74	GX-B1378/22-F-23124	2023. 5. 15	所检项目合格	 A photograph showing two laboratory technicians in white lab coats and masks working at a laboratory bench. They are positioned in front of a biosafety cabinet. The bench is cluttered with various pieces of laboratory equipment, including a green instrument, a water bottle, and some papers. A date stamp '2023/5/7' is visible in the bottom right corner of the image.


75	GX-B1377/22-F-23151	2023. 5. 15	所检项目合格	 A photograph showing two female technicians in a laboratory or inspection room. They are wearing light grey work jackets with the logo '中检公信' (China Inspection and Certification) on the back. One technician is wearing a blue surgical mask. They are standing next to a piece of equipment with a prominent red screen. The date '2023/5/17' is visible in the bottom right corner of the photo.
76	GX-B1377/22-F-23152	2023. 5. 15	所检项目合格	 A photograph showing two female technicians in a laboratory or inspection room, similar to the one above. They are wearing light grey work jackets with the logo '中检公信' (China Inspection and Certification) on the back. One technician is wearing a blue surgical mask. They are standing next to a piece of equipment with a prominent red screen. The date '2023/5/17' is visible in the bottom right corner of the photo.


77	GX-B1377/22-F-23153	2023. 5. 15	所检项目合格	
78	GX-B1377/22-F-23154	2023. 5. 15	所检项目合格	

79	GX-B1377/22-F-23155	2023. 5. 15	所检项目合格	 A photograph showing two individuals in a laboratory or clinical setting. They are standing near a piece of equipment, possibly a biosafety cabinet or a specialized workstation. One person appears to be operating the equipment while the other observes. The date stamp in the bottom right corner of the image is 2023/5/7.
80	GX-B1378/22-F-23132	2023. 5. 16	所检项目合格	 A photograph showing two individuals in a laboratory or clinical setting. They are standing near a piece of equipment, possibly a biosafety cabinet or a specialized workstation. One person appears to be operating the equipment while the other observes. The date stamp in the bottom right corner of the image is 2023/5/10.

81	GX-B1378/22-F-23133	2023. 5. 16	所检项目合格	 A photograph showing two individuals in a laboratory or office environment. One person is standing and looking at a piece of equipment on a desk, while the other is partially visible behind them. The scene is brightly lit with natural light from a window.
82	GX-B1377/22-F-23163	2023. 5. 16	所检项目合格	 A photograph showing two individuals in a laboratory or office environment. They are standing at a desk with a computer monitor and other equipment. One person appears to be operating the equipment. The scene is brightly lit with natural light from a window.

83	GX-B1377/22-F-23164	2023. 5. 16	所检项目合格	 A photograph showing two individuals wearing face masks and light-colored jackets in a laboratory or office environment. They are standing behind a blue table, looking at a computer monitor. A window with yellow curtains is visible in the background. A timestamp '2023/5/16' is present in the bottom right corner of the image.
84	GX-B1377/22-F-23165	2023. 5. 16	所检项目合格	 A photograph showing two individuals wearing face masks and light-colored jackets in a laboratory or office environment. They are standing behind a blue table, looking at a computer monitor. A window with yellow curtains is visible in the background. A timestamp '2023/5/16' is present in the bottom right corner of the image.

85	GX-B1377/22-F-23166	2023. 5. 16	所检项目合格	 A photograph showing two individuals in a laboratory or office environment. They are wearing light-colored lab coats and face masks. They are standing near a desk with a computer monitor. One person is pointing at the screen while the other looks on. The room has a window with yellow curtains and a radiation warning sign on the wall. A timestamp '2023/5/10' is visible in the bottom right corner of the image.
86	GX-B1377/22-F-23170	2023. 5. 17	所检项目合格	 A photograph showing a person in a lab coat and face mask working with a piece of equipment. The person is wearing white gloves and is focused on a task. The equipment has a red interior. The setting is a laboratory or office with other equipment visible in the background. A timestamp '2023/5/11' is visible in the bottom right corner of the image.

87	GX-B1377/22-F-23171	2023. 5. 17	所检项目合格	
88	GX-B1377/22-F-23172	2023. 5. 17	所检项目合格	

89	GX-B1377/22-F-23173	2023. 5. 17	所检项目合格	
90	GX-B1377/22-F-23174	2023. 5. 17	所检项目合格	

91	GX-B1377/22-F-23175	2023. 5. 17	所检项目合格	
92	GX-B1377/22-F-23176	2023. 5. 17	所检项目合格	