

序号	报告编号	发布日期	结论	影像资料
494	GX-B1423/20-Y-233586	2023年6月19日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two workers wearing safety gear are standing next to the truck. The truck has the number '5' on its side. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.
495	GX-B1423/20-Y-233587	2023年6月19日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two workers wearing safety gear are standing next to the truck. The truck has the number '5' on its side. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.

496	GX-B1423/20-Y-233588	2023年6月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.
497	GX-B1423/20-Y-233589	2023年6月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.
498	GX-B1423/20-Y-233590	2023年6月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.

499	GX-B1423/20-Y-233591	2023年6月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has the number '499' on its side. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.
500	GX-B1423/20-Y-233592	2023年6月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has the number '500' on its side. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.
501	GX-B1423/20-Y-233593	2023年6月19日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has the number '501' on its side. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.

502	GX-B1423/20-Y-233594	2023年6月19日	综合判定：合格	 A yellow dump truck is shown from a side profile, parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.
503	GX-B1423/20-Y-233595	2023年6月19日	综合判定：合格	 A yellow dump truck is shown from a side profile, parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.
504	GX-B1423/20-Y-233596	2023年6月19日	综合判定：合格	 A yellow dump truck is shown from a side profile, parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has a large dump body and multiple axles. A small yellow timestamp '2023/6/19' is visible in the bottom right corner of the image.

505	GX-B1423/20-Y-233597	2023年6月19日	综合判定：合格	 A yellow dump truck with a large dump body, parked on a dirt surface. Two workers in safety gear are standing near the front. The truck has the number '169' on its side.
506	GX-B1423/20-Y-233598	2023年6月19日	综合判定：合格	 A yellow dump truck with a large dump body, parked on a dirt surface. Two workers in safety gear are standing near the front. The truck has the number '186' on its side.
507	GX-B1423/20-Y-233599	2023年6月19日	综合判定：合格	 A yellow dump truck with a large dump body, parked on a dirt surface. Two workers in safety gear are standing near the front. The truck has the number '188' on its side.

508	GX-B1423/20-Y-233600	2023年6月19日	综合判定：合格	
509	GX-B1495/20-Y-231231~ 231245	2023年6月19日	本次共检高压开关设备 15台，15台高压开关设备所 检项目合格。	
510	GX-B1495/20-Y-231282~ 231298	2023年6月19日	本次共检高压开关设备 17台，17台高压开关设备所 检项目合格。	

511	GX-B1495/20-Y-231438~ 231446	2023年6月19日	本次共检高压开关设备 9台，9台高压开关设备所检 项目合格。	
512	GX-B1495/20-Y-231447~ 231462	2023年6月19日	本次共检高压开关设备 16台，16台高压开关设备所 检项目合格。	
513	GX-B1495/20-Y-231463~ 231471	2023年6月19日	本次共检高压开关设备 9台，9台高压开关设备所检 项目合格。	

514	GX-B1495/20-Y-231472~ 231481	2023年6月19日	本次共检高压开关设备 10台，10台高压开关设备所 检项目合格。	
515	GX-B1495/20-Y-231435~ 231437	2023年6月19日	本次共检高压开关设备 3台，3台高压开关设备所检 项目合格。	
516	GX-B1495/20-Y-231264~ 231281	2023年6月19日	本次共检高压开关设备 18台，18台高压开关设备所 检项目合格。	

517	GX-B1495/20-Y-231246~ 231263	2023年6月19日	本次共检高压开关设备 18台，18台高压开关设备所 检项目合格。	
518	GX-B1350/21-Y-23013	2023年6月17日	本次共检接地装置9处，9处 接地装置所检项目合格。	
519	GX-B1350/21-Y-23014	2023年6月17日	本次共检接地装置3处，3处 接地装置所检项目合格。	

520	GX-B1350/21-Y-23015	2023年6月17日	本次共检接地装置2处，2处接地装置所检项目合格	
521	GX-B1312/20-Y-23314~23315	2023年6月17日	本次共检电力变压器2台，2台电力变压器所检项目合格。	
522	GX-B1312/20-Y-23316~23318	2023年6月17日	本次共检电力变压器3台，3台电力变压器所检项目合格。	

523	GX-B1312/20-Y-23319~23322	2023年6月17日	本次共检电力变压器4台，4台电力变压器所检项目合格。 。	 A photograph showing several workers in blue uniforms and red hard hats inspecting a large red electrical transformer. One worker is using a handheld device. A date stamp '2023/5/23' is visible in the bottom right corner.
524	GX-B1312/20-Y-23323~23324	2023年6月17日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	 A photograph of a worker in a grey jacket and red hard hat kneeling on the floor, inspecting a piece of equipment. A date stamp '2023/5/23' is visible in the bottom right corner.
525	GX-B1312/20-Y-23325~23337	2023年6月17日	本次共检电力变压器13台，13台电力变压器所检项目合格。 格。	 A photograph showing multiple workers in blue uniforms and red hard hats working on several red electrical transformers. A date stamp '2023/5/25' is visible in the bottom right corner.

526	GX-B1312/20-Y-23338~23341	2023年6月17日	本次共检电力变压器4台，4台电力变压器所检项目合格。 。	
527	GX-B1312/20-Y-23342~23347	2023年6月17日	本次共检电力变压器6台，6台电力变压器所检项目合格。 。	
528	GX-B1312/20-Y-23348~23349	2023年6月17日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	

529	GX-B1312/20-Y-23350~23354	2023年6月17日	<p>本次共检电力变压器5台，5台电力变压器所检项目合格。</p> <p>。</p>	
530	GX-B1328/20-Y-23052	2023年6月17日	<p>本次共检绝缘胶垫24件，24件绝缘胶垫合格</p>	
531	GX-B1328/20-Y-23055	2023年6月17日	<p>本次共检验电器10支，10支验电器合格。</p>	

532	GX-B1328/20-Y-23056	2023年6月17日	本次共检便携式接地和接地短路装置5组，5组便携式接地和接地短路装置合格。	
533	GX-B1328/20-Y-23057	2023年6月17日	本次共检绝缘杆5支，5支绝缘杆合格。	
534	GX-B1328/20-Y-23053	2023年6月17日	本次共检绝缘鞋28只，28只绝缘鞋合格。	


535	GX-B1328/20-Y-23054	2023年6月17日	本次共检绝缘手套26只，26只绝缘手套合格。	
536	GX-B1495/20-Y-231414~231424	2023年6月18日	本次共检高压开关设备11台，11台高压开关设备所检项目合格。	
537	GX-B1495/20-Y-231425~231434	2023年6月18日	本次共检高压开关设备10台，10台高压开关设备所检项目合格。	

538	GX-B1547/20-Y-23256~23259	2023年6月18日	本次共检继电保护装置4台，4台继电保护装置所检项目合格。	
539	GX-B1547/20-Y-23260~23262	2023年6月18日	本次共检继电保护装置3台，3台继电保护装置所检项目合格。	
540	GX-B1329/21-Y-23159~23171	2023年6月18日	本次共检氧化锌避雷器13组，13组氧化锌避雷器所检项目合格。	

541	GX-B1329/21-Y-23172~23186	2023年6月18日	<p>本次共检氧化锌避雷器 15组，15组氧化锌避雷器所 检项目合格。</p>	
542	GX-B1329/21-Y-23187~23189	2023年6月18日	<p>本次共检氧化锌避雷器 3组，3组氧化锌避雷器所检 项目合格。</p>	
543	GX-B1329/21-Y-23190~23191	2023年6月18日	<p>本次共检氧化锌避雷器 2组，2组氧化锌避雷器所检 项目合格。</p>	

544	GX-B1495/20-Y-231409~ 231411	2023年6月18日	本次共检高压交流断路器 3台，3台高压交流断路器所 检项目合格。	
545	GX-B1495/20-Y-231412~ 231413	2023年6月18日	本次共检高压交流断路器 2台，2台高压交流断路器所 检项目合格。	
546	GX-B1332/21-Y-23013~23021	2023年6月18日	本次共检电力电容器9台，9 台电力电容器所检项目合格 。	

547	GX-B1332/21-Y-23022~23030	2023年6月18日	<p>本次共检电力电容器9台，9台电力电容器所检项目合格。</p>	
548	GX-B1306/21-Y-23079	2023年6月19日	<p>所检项目合格。</p>	
549	GX-B1521/20-Y-23367	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

550	GX-B1521/20-Y-23368	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
551	GX-B1521/20-Y-23303	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
552	GX-B1521/20-Y-23304	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

553	GX-B1521/20-Y-23305	2023年6月20日	<p>依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
554	GX-B1521/20-Y-23306	2023年6月20日	<p>依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
555	GX-B1521/20-Y-23307	2023年6月20日	<p>依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

556	GX-B1521/20-Y-23359	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
557	GX-B1521/20-Y-23360	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
558	GX-B1521/20-Y-23361	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

559	GX-B1521/20-Y-23362	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
560	GX-B1521/20-Y-23363	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
561	GX-B1521/20-Y-23364	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

562	GX-B1521/20-Y-23365	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
563	GX-B1521/20-Y-23366	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
564	GX-B1328/20-Y-23058	2023年6月19日	<p>本次共检绝缘胶垫82件，82件绝缘胶垫合格。</p>	

565	GX-B1328/20-Y-23059	2023年6月19日	本次共检验电器21支，21支 验电器合格。	
566	GX-B1328/20-Y-23083	2023年6月19日	所检项目合格。	
567	GX-B1521/20-Y-23369	2023年6月20日	依据GB/T 9139-2018 《土 方机械 液压挖掘机 技术条 件》 GB/ T7586-2018 《土方机 械 液压挖掘机 试验方法 》，所检项目合格。	

568	GX-B1521/20-Y-23370	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/ T7586-2019 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
569	GX-B1521/20-Y-23371	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/ T7586-2020 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
570	GX-B1521/20-Y-23372	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/ T7586-2021 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

571	GX-B1521/20-Y-23373	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/ T7586-2022 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
572	GX-B1521/20-Y-23374	2023年6月20日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/ T7586-2023 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
573	GX-B1521/20-Y-23290	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

574	GX-B1521/20-Y-23291	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
575	GX-B1521/20-Y-23292	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
576	GX-B1521/20-Y-23293	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

577	GX-B1521/20-Y-23294	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
578	GX-B1521/20-Y-23295	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
579	GX-B1521/20-Y-23296	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

580	GX-B1521/20-Y-23297	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
581	GX-B1521/20-Y-23298	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
582	GX-B1521/20-Y-23299	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

583	GX-B1521/20-Y-23300	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
584	GX-B1521/20-Y-23301	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
585	GX-B1521/20-Y-23302	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

586	GX-B1521/20-Y-23329	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
587	GX-B1521/20-Y-23330	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
588	GX-B1521/20-Y-23331	2023年6月21日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	