

序号	报告编号	发布日期	结论	影像资料
672	GX-B1423/20-Y-233082	2023年6月25日	综合判定：合格	
673	GX-B1423/20-Y-233083	2023年6月25日	综合判定：合格	

674	GX-B1423/20-Y-233084	2023年6月25日	综合判定：合格	 <p>A red dump truck with the number 772 on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the photo.</p>
675	GX-B1423/20-Y-233085	2023年6月25日	综合判定：合格	 <p>A red dump truck with the number 776 on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the photo.</p>

676	GX-B1423/20-Y-233086	2023年6月25日	综合判定：合格	
677	GX-B1423/20-Y-233087	2023年6月25日	综合判定：合格	

678	GX-B1423/20-Y-233088	2023年6月25日	综合判定：合格	
679	GX-B1423/20-Y-233089	2023年6月25日	综合判定：合格	

680	GX-B1423/20-Y-233090	2023年6月25日	综合判定：合格	 <p>A red dump truck with license plate 桂A-1757 and number 757. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the photo.</p>
681	GX-B1423/20-Y-233091	2023年6月25日	综合判定：合格	 <p>A red dump truck with license plate 桂A-1773 and number 775. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the photo.</p>

682	GX-B1423/20-Y-233092	2023年6月25日	综合判定：合格	 <p>A photograph of a red dump truck with a white cab and a large red dump body. Two workers in safety gear (hard hats and high-visibility vests) are standing in front of the truck. The truck has 'MTB6L7' and '771' visible on its side. A yellow date stamp '2023/5/11' is in the bottom right corner.</p>
683	GX-B1423/20-Y-233093	2023年6月25日	综合判定：合格	 <p>A photograph of a red dump truck, similar to the one in the first row, with a white cab and a large red dump body. Two workers in safety gear are standing in front of it. The truck has 'MTB6L7' and '771' visible on its side. A yellow date stamp '2023/5/11' is in the bottom right corner.</p>

684	GX-B1423/20-Y-233094	2023年6月25日	综合判定：合格	 <p>A photograph of a red dump truck with license plate H-1768. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the image.</p>
685	GX-B1423/20-Y-233095	2023年6月25日	综合判定：合格	 <p>A photograph of a red dump truck with license plate H-1769. Two workers in safety gear stand in front of the truck. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the image.</p>

686	GX-B1423/20-Y-233096	2023年6月25日	综合判定：合格	 <p>A red dump truck with the number 763 on its side is parked on a dirt surface. Two workers wearing safety gear are standing next to it. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the photo.</p>
687	GX-B1423/20-Y-233097	2023年6月25日	综合判定：合格	 <p>A red dump truck with the number 762 on its side is parked on a dirt surface. Two workers wearing safety gear are standing next to it. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the photo.</p>

688	GX-B1423/20-Y-233098	2023年6月25日	综合判定：合格	
689	GX-B1423/20-Y-233099	2023年6月25日	综合判定：合格	

690	GX-B1423/20-Y-233100	2023年6月25日	综合判定：合格	
691	GX-B1423/20-Y-233101	2023年6月25日	综合判定：合格	

692	GX-B1423/20-Y-233102	2023年6月25日	综合判定：合格	
693	GX-B1423/20-Y-233103	2023年6月25日	综合判定：合格	

694	GX-B1423/20-Y-233104	2023年6月25日	综合判定：合格	 <p>A red dump truck with license plate 770 is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/12' is visible in the bottom right corner of the image.</p>
695	GX-B1423/20-Y-233105	2023年6月25日	综合判定：合格	 <p>A red dump truck with license plate 774 is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/12' is visible in the bottom right corner of the image.</p>

696	GX-B1423/20-Y-233106	2023年6月25日	综合判定：合格	
697	GX-B1423/20-Y-233107	2023年6月25日	综合判定：合格	

698	GX-B1423/20-Y-233108	2023年6月25日	综合判定：合格	
699	GX-B1423/20-Y-233109	2023年6月25日	综合判定：合格	

700	GX-B1423/20-Y-233110	2023年6月25日	综合判定：合格	
701	GX-B1423/20-Y-233111	2023年6月25日	综合判定：合格	

702	GX-B1423/20-Y-233112	2023年6月25日	综合判定：合格	
703	GX-B1423/20-Y-233113	2023年6月25日	综合判定：合格	

704	GX-B1423/20-Y-233114	2023年6月25日	综合判定：合格	
705	GX-B1423/20-Y-233115	2023年6月25日	综合判定：合格	

706	GX-B1423/20-Y-233116	2023年6月25日	综合判定：合格	
707	GX-B1423/20-Y-233117	2023年6月25日	综合判定：合格	

708	GX-B1423/20-Y-233118	2023年6月25日	综合判定：合格	
709	GX-B1423/20-Y-233119	2023年6月25日	综合判定：合格	

710	GX-B1423/20-Y-233120	2023年6月25日	综合判定：合格	
711	GX-B1423/20-Y-233121	2023年6月25日	综合判定：合格	

712	GX-B1423/20-Y-233122	2023年6月25日	综合判定：合格	
713	GX-B1423/20-Y-233123	2023年6月25日	综合判定：合格	

714	GX-B1423/20-Y-233124	2023年6月25日	综合判定：合格	
715	GX-B1423/20-Y-233125	2023年6月25日	综合判定：合格	

716	GX-B1423/20-Y-233126	2023年6月25日	综合判定：合格	
717	GX-B1423/20-Y-233127	2023年6月25日	综合判定：合格	

718	GX-B1423/20-Y-233128	2023年6月25日	综合判定：合格	
719	GX-B1423/20-Y-233129	2023年6月25日	综合判定：合格	

720	GX-B1423/20-Y-233130	2023年6月25日	综合判定：合格	
721	GX-B1423/20-Y-233131	2023年6月25日	综合判定：合格	

722	GX-B1423/20-Y-233132	2023年6月25日	综合判定：合格	
723	GX-B1423/20-Y-233133	2023年6月25日	综合判定：合格	

724	GX-B1423/20-Y-233134	2023年6月25日	综合判定：合格	 <p>A yellow dump truck is shown from a front-three-quarter view. The license plate reads 'BM-四喜创世-1036'. Two men are standing in front of the truck: one in a grey work jacket and red helmet, and another in a red jumpsuit and red helmet. A yellow timestamp '2023/5/13' is visible in the bottom right corner of the photo.</p>
725	GX-B1423/20-Y-233135	2023年6月25日	综合判定：合格	 <p>A yellow dump truck is shown from a front-three-quarter view. The license plate reads 'H-1783'. Two men are standing in front of the truck: one in a grey work jacket and red helmet, and another in a red jumpsuit and white helmet. A yellow timestamp '2023/5/13' is visible in the bottom right corner of the photo.</p>

726	GX-B1423/20-Y-233136	2023年6月25日	综合判定：合格	
727	GX-B1423/20-Y-233137	2023年6月25日	综合判定：合格	

728	GX-B1423/20-Y-233138	2023年6月25日	综合判定：合格	
729	GX-B1423/20-Y-233139	2023年6月25日	综合判定：合格	

730	GX-B1423/20-Y-233140	2023年6月25日	综合判定：合格	
731	GX-B1423/20-Y-233141	2023年6月25日	综合判定：合格	

732	GX-B1423/20-Y-233142	2023年6月25日	综合判定：合格	
733	GX-B1423/20-Y-233143	2023年6月25日	综合判定：合格	

734	GX-B1423/20-Y-233144	2023年6月25日	综合判定：合格	
735	GX-B1423/20-Y-233145	2023年6月25日	综合判定：合格	

736	GX-B1423/20-Y-233146	2023年6月25日	综合判定：合格	
737	GX-B1423/20-Y-233147	2023年6月25日	综合判定：合格	

738	GX-B1423/20-Y-233148	2023年6月25日	综合判定：合格	
739	GX-B1423/20-Y-233149	2023年6月25日	综合判定：合格	

740	GX-B1423/20-Y-233150	2023年6月25日	综合判定：合格	
741	GX-B1423/20-Y-233151	2023年6月25日	综合判定：合格	

742	GX-B1423/20-Y-233152	2023年6月25日	综合判定：合格	
743	GX-B1423/20-Y-233153	2023年6月25日	综合判定：合格	

744	GX-B1423/20-Y-233154	2023年6月25日	综合判定：合格	
745	GX-B1423/20-Y-233155	2023年6月25日	综合判定：合格	

746	GX-B1423/20-Y-233156	2023年6月25日	综合判定：合格	
747	GX-B1423/20-Y-233157	2023年6月25日	综合判定：合格	

748	GX-B1423/20-Y-233158	2023年6月25日	综合判定：合格	
749	GX-B1423/20-Y-233159	2023年6月25日	综合判定：合格	

750	GX-B1423/20-Y-233160	2023年6月25日	综合判定：合格	
751	GX-B1423/20-Y-233161	2023年6月25日	综合判定：合格	

752	GX-B1423/20-Y-233162	2023年6月25日	综合判定：合格	 <p>A yellow MT96L dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow date stamp '2023/5/14' is visible in the bottom right corner of the photo.</p>
753	GX-B1423/20-Y-233163	2023年6月25日	综合判定：合格	 <p>A yellow MT96L dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow date stamp '2023/5/14' is visible in the bottom right corner of the photo.</p>

754	GX-B1423/20-Y-233164	2023年6月25日	综合判定：合格	 <p>A photograph of a yellow MT98 H-1723 truck. Two workers, one in a grey uniform and one in a red uniform, are standing in front of the truck. The date stamp '2023/5/14' is visible in the bottom right corner of the image.</p>
755	GX-B1423/20-Y-233165	2023年6月25日	综合判定：合格	 <p>A photograph of a yellow MT96L truck. Two workers, one in a red uniform and one in a grey uniform, are standing in front of the truck. The date stamp '2023/5/14' is visible in the bottom right corner of the image.</p>

756	GX-B1423/20-Y-233166	2023年6月25日	综合判定：合格	
757	GX-B1423/20-Y-233167	2023年6月25日	综合判定：合格	

758	GX-B1423/20-Y-233168	2023年6月25日	综合判定：合格	
759	GX-B1423/20-Y-233169	2023年6月25日	综合判定：合格	

760	GX-B1423/20-Y-233170	2023年6月25日	综合判定：合格	
761	GX-B1423/20-Y-233171	2023年6月25日	综合判定：合格	

762	GX-B1423/20-Y-233172	2023年6月25日	综合判定：合格	
763	GX-B1423/20-Y-233173	2023年6月25日	综合判定：合格	

764	GX-B1423/20-Y-233174	2023年6月25日	综合判定：合格	
765	GX-B1423/20-Y-233175	2023年6月25日	综合判定：合格	

766	GX-B1423/20-Y-233176	2023年6月25日	综合判定：合格	
767	GX-B1423/20-Y-233177	2023年6月25日	综合判定：合格	

768	GX-B1423/20-Y-233178	2023年6月25日	综合判定：合格	
769	GX-B1423/20-Y-233179	2023年6月25日	综合判定：合格	

770	GX-B1423/20-Y-233180	2023年6月25日	综合判定：合格	
771	GX-B1423/20-Y-233181	2023年6月25日	综合判定：合格	

772	GX-B1423/20-Y-233182	2023年6月25日	综合判定：合格	 <p>A yellow dump truck with the number '2005' on its side. Two workers, one in a red suit and one in a white suit, are standing in front of the truck. The truck has 'MT85' and 'H-1504' on its side. A yellow timestamp '2023/6/14' is visible in the bottom right corner of the photo.</p>
773	GX-B1423/20-Y-233183	2023年6月25日	综合判定：合格	 <p>A yellow dump truck with the number '2004' on its side. Two workers, one in a white suit and one in a red suit, are standing in front of the truck. The truck has 'MT85' and 'H-1504' on its side. A yellow timestamp '2023/6/14' is visible in the bottom right corner of the photo.</p>

774	GX-B1423/20-Y-233184	2023年6月25日	综合判定：合格	 <p>A yellow dump truck with the number '2002' painted on its side. Two workers, one in a grey uniform and one in a red uniform, stand in front of the truck. The date '2023/5/14' is visible in the bottom right corner of the photo.</p>
775	GX-B1423/20-Y-233185	2023年6月25日	综合判定：合格	 <p>A yellow dump truck with the number '2001' painted on its side. Two workers, one in a red uniform and one in a grey uniform, stand in front of the truck. The date '2023/5/14' is visible in the bottom right corner of the photo.</p>

776	GX-B1423/20-Y-233186	2023年6月25日	综合判定：合格	 A yellow dump truck is parked in an open area. Two workers in red and grey uniforms are standing next to it. A yellow date stamp '2023/5/14' is visible in the bottom right corner of the photo.
777	GX-B1423/20-Y-233187	2023年6月25日	综合判定：合格	 A yellow dump truck is parked in an open area. A worker in a grey uniform is standing next to it. The number '2009' is visible on the side of the truck. A yellow date stamp '2023/5/14' is visible in the bottom right corner of the photo.

778	GX-B1423/20-Y-233188	2023年6月25日	综合判定：合格	
-----	----------------------	------------	---------	---