

序号	报告编号	发布日期	结论	影像资料
237	GX-B1508/22-A-23001	2023/7/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
238	GX-B1364/22-A-23610	2023/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
239	GX-B1366/20-A-23084	2023/7/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
240	GX-B1366/20-A-23081	2023/7/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
241	GX-B1366/20-A-23082	2023/7/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
242	GX-B1366/20-A-23083	2023/7/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
243	GX-B1366/20-A-23085	2023/7/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
244	GX-B1363/22-A-23307	2023/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
245	GX-B1363/22-A-23308	2023/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
246	GX-B1364/22-A-23608	2023/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
247	GX-B1364/22-A-23605	2023/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
248	GX-B1364/22-A-23606	2023/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
249	GX-B1364/22-A-23609	2023/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
250	GX-B1364/22-A-23607	2023/7/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
251	GX-B1363/22-A-23314	2023/7/25	所检项目合格。	 <p>The photograph shows two technicians in light blue work shirts and blue gloves inspecting a large, rusted industrial furnace. The furnace has a conical top and two doors. One technician is on the left, looking into the furnace, while the other is on the right, holding a door. A date stamp '2023/07/14' is visible in the bottom right corner of the image. The background shows a window with a view of trees.</p>

序号	报告编号	发布日期	结论	影像资料
252	GX-B1363/22-A-23313	2023/7/25	所检项目合格。	 A photograph showing two men in light blue work shirts inspecting a large, rusted industrial furnace. One man is on the left, looking at the furnace, and the other is on the right, wearing blue gloves and glasses, looking closely at the furnace door. The furnace has a large vertical pipe on top and a date stamp '2023/07/13' in the bottom right corner. There are yellow warning signs on the furnace doors.

序号	报告编号	发布日期	结论	影像资料
253	GX-B1363/22-A-23312	2023/7/24	所检项目合格。	 <p>2023/07/13</p>

序号	报告编号	发布日期	结论	影像资料
254	GX-B1463/22-A-23003	2023/7/25	所检项目合格。	 <p>2023/06/16</p>

序号	报告编号	发布日期	结论	影像资料
255	GX-B1363/22-A-23299	2023/7/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
256	GX-B1363/22-A-23298	2023/7/25	所检项目合格。	 <p>The photograph shows two men in light blue work shirts inspecting a large, rusted metal cabinet. One man is wearing blue gloves. A white chimney pipe extends from the top of the cabinet. A green trash bin is visible on the left. A date stamp '2023/07/04' is in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
257	GX-B1363/22-A-23300	2023/7/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
258	GX-B1363/22-A-23296	2023/7/25	所检项目合格。	 <p>The photograph shows two male technicians in white short-sleeved uniforms working on a large, rusted industrial furnace. The technician on the right is wearing blue gloves and is holding a large metal panel that is part of the furnace's structure. The technician on the left is looking into the furnace's interior. The furnace has a prominent vertical pipe on top. In the background, there is a window with a view of green trees. A date stamp '2023/07/03' is overlaid in the bottom right corner of the image. The back of the technician on the left has a logo and the Chinese characters '松信' (Songxin) on his uniform.</p>

序号	报告编号	发布日期	结论	影像资料
259	GX-B1367/22-A-23076	2023/7/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
260	GX-B1363/22-A-23306	2023/7/25	所检项目合格。	 A photograph showing two workers in light blue uniforms inspecting a large, rusted industrial furnace. The furnace has a tall, white, cylindrical chimney pipe extending upwards. The workers are wearing gloves and are looking into the open doors of the furnace. A date stamp '2023/07/07' is visible in the bottom right corner of the image. The background shows a window with a view of greenery outside.

序号	报告编号	发布日期	结论	影像资料
261	GX-B1363/22-A-23264	2023/7/25	所检项目合格。	