

序号	报告编号	发布日期	结论	影像资料
1	GX-B1300/20-5-23019	2023/8/4	所检项目合格。	 A photograph showing two workers wearing red hard hats and light-colored shirts. They are standing on a yellow and black striped safety platform, inspecting a large green industrial machine with various pipes and components. A yellow timestamp '2023/7/14' is visible in the bottom right corner of the image.
2	GX-B1305/21-5-23005	2023. 8. 8	综合判定：合格。	 A photograph of a worker in a dark uniform and white hard hat operating a control panel. The panel has a screen and several buttons. The setting appears to be an industrial or underground environment with concrete walls. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the image.

3	GX-B1350/21-5-23061	2023. 8. 8	本次共检接地装置4处，4处接地装置所检项目合格。	 <p>2023/8/4</p>
4	GX-B1321/20-5-23869~23874	2023. 8. 8	本次共检电力电缆6条，6条电力电缆所检项目合格。	 <p>2023. 08. 05</p>
5	GX-B1495/20-5-231723~231729	2023. 8. 8	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	 <p>2023/08/05</p>

6	GX-B1416/22-5-23081	2023. 8. 9	合格	 A black and white photograph of a worker wearing a hard hat and a safety vest with reflective strips. The worker is holding a long-handled tool, possibly a pry bar or a similar instrument, and is focused on a task in a dark, industrial environment. The date '2023. 5. 16' is visible in the bottom right corner of the photo.
7	GX-B1416/22-5-23082	2023. 8. 9	合格	 A black and white photograph of a worker wearing a hard hat and a safety vest with reflective strips. The worker is looking down at a handheld device, possibly a tablet or a specialized tool, in a dark industrial setting. The date '2023. 5. 16' is visible in the bottom right corner of the photo.
8	GX-B1416/22-5-23083	2023. 8. 9	合格	 A black and white photograph of a worker wearing a hard hat and a safety vest with reflective strips. The worker is holding a handheld device and appears to be using it in a dark industrial setting. The date '2023. 5. 16' is visible in the bottom right corner of the photo.

9	GX-B1416/22-5-23084	2023. 8. 9	合格	 A worker in a white uniform and hard hat is operating a tool on a metal structure at night. The worker is wearing a headlamp. The date 2023. 5. 16 is visible in the bottom right corner of the image.
10	GX-B1416/22-5-23085	2023. 8. 9	合格	 A worker in a white uniform and hard hat is using a handheld device on a metal structure at night. The worker is wearing a headlamp. The date 2023. 5. 17 is visible in the bottom right corner of the image.
11	GX-B1310/21-5-23215	2023. 8. 10	符合标准要求。	 A worker in a white uniform and hard hat is operating a large piece of machinery in a factory setting. The worker is wearing a headlamp. The date 2023/6/19 is visible in the bottom right corner of the image.

12	GX-B1310/21-5-23216	2023. 8. 10	符合标准要求。	
13	GX-B1310/21-5-23217	2023. 8. 10	符合标准要求。	
14	GX-B1310/21-5-23218	2023. 8. 10	符合标准要求。	

15	GX-B1310/21-5-23219	2023. 8. 10	符合标准要求。	 <p>2023/6/23</p>
16	GX-B1310/21-5-23220	2023. 8. 10	符合标准要求。	 <p>2023/6/23</p>
17	GX-B1310/21-5-23221	2023. 8. 10	符合标准要求。	 <p>2023/6/23</p>

18	GX-B1303/21-5-23007	2023. 8. 11	所检项目合格。	
19	GX-B1415/22-5-23008	2023. 08. 11	综合判定：合格。	
20	GX-B1306/21-5-23056	2023. 8. 10	所检项目合格。	