

序号	报告编号	发布日期	结论	影像资料
229	GX-B1415/22-Y-23013	2023年8月7日	综合判定：合格。 。	 A photograph showing three workers in orange safety suits and helmets in an industrial environment. One worker on the left is looking at a handheld device. The date stamp '2023/7/19' is visible in the bottom right corner of the image.
230	GX-B1423/20-Y-234587	2023年8月7日	综合判定：合格	 A photograph of a large grey dump truck parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The date stamp '2023/7/13' is visible in the bottom right corner of the image.

231	GX-B1423/20-Y-234588	2023年8月7日	综合判定：合格		
232	GX-B1423/20-Y-234589	2023年8月7日	综合判定：合格		

233	GX-B1423/20-Y-234590	2023年8月7日	综合判定：合格		
234	GX-B1423/20-Y-234591	2023年8月7日	综合判定：合格		

235	GX-B1423/20-Y-234592	2023年8月7日	综合判定：合格		
236	GX-B1423/20-Y-234593	2023年8月7日	综合判定：合格		

237	GX-B1423/20-Y-234594	2023年8月7日	综合判定：合格		
238	GX-B1423/20-Y-234595	2023年8月7日	综合判定：合格		

239	GX-B1423/20-Y-234596	2023年8月7日	综合判定：合格	
240	GX-B1423/20-Y-234597	2023年8月7日	综合判定：合格	

241	GX-B1423/20-Y-234598	2023年8月7日	综合判定：合格		
242	GX-B1423/20-Y-234599	2023年8月7日	综合判定：合格		

243	GX-B1423/20-Y-234600	2023年8月7日	综合判定：合格	
244	GX-B1423/20-Y-234601	2023年8月7日	综合判定：合格	

245	GX-B1423/20-Y-234602	2023年8月7日	综合判定：合格	
246	GX-B1423/20-Y-234603	2023年8月7日	综合判定：合格	

247	GX-B1423/20-Y-234604	2023年8月7日	综合判定：合格	
248	GX-B1423/20-Y-234605	2023年8月7日	综合判定：合格	

249	GX-B1423/20-Y-234606	2023年8月7日	综合判定：合格	
250	GX-B1423/20-Y-234607	2023年8月7日	综合判定：合格	

251	GX-B1423/20-Y-234608	2023年8月7日	综合判定：合格		
252	GX-B1423/20-Y-234609	2023年8月7日	综合判定：合格		

253	GX-B1423/20-Y-234610	2023年8月7日	综合判定：合格		
254	GX-B1423/20-Y-234611	2023年8月7日	综合判定：合格		

255	GX-B1423/20-Y-234612	2023年8月7日	综合判定：合格	
256	GX-B1423/20-Y-234613	2023年8月7日	综合判定：合格	

257	GX-B1423/20-Y-234614	2023年8月7日	综合判定：合格		
258	GX-B1423/20-Y-234615	2023年8月7日	综合判定：合格		

259	GX-B1423/20-Y-234616	2023年8月7日	综合判定：合格	
260	GX-B1423/20-Y-234617	2023年8月7日	综合判定：合格	

261	GX-B1423/20-Y-234618	2023年8月7日	综合判定：合格	
262	GX-B1423/20-Y-234619	2023年8月7日	综合判定：合格	

263	GX-B1423/20-Y-234620	2023年8月7日	综合判定：合格	
264	GX-B1423/20-Y-234621	2023年8月7日	综合判定：合格	

265	GX-B1423/20-Y-234622	2023年8月7日	综合判定：合格	
266	GX-B1423/20-Y-234623	2023年8月7日	综合判定：合格	

267	GX-B1423/20-Y-234624	2023年8月7日	综合判定：合格		
268	GX-B1423/20-Y-234625	2023年8月7日	综合判定：合格		

269	GX-B1423/20-Y-234626	2023年8月7日	综合判定：合格		
270	GX-B1423/20-Y-234627	2023年8月7日	综合判定：合格		

271	GX-B1423/20-Y-234628	2023年8月7日	综合判定：合格		
272	GX-B1423/20-Y-234629	2023年8月7日	综合判定：合格		

273	GX-B1423/20-Y-234630	2023年8月7日	综合判定：合格		
274	GX-B1423/20-Y-234631	2023年8月7日	综合判定：合格		

275	GX-B1423/20-Y-234632	2023年8月7日	综合判定：合格	
276	GX-B1423/20-Y-234633	2023年8月7日	综合判定：合格	

277	GX-B1423/20-Y-234634	2023年8月7日	综合判定：合格	
278	GX-B1423/20-Y-234635	2023年8月7日	综合判定：合格	

279	GX-B1423/20-Y-234636	2023年8月7日	综合判定：合格		
280	GX-B1423/20-Y-234637	2023年8月7日	综合判定：合格		

281	GX-B1423/20-Y-234638	2023年8月7日	综合判定：合格	
282	GX-B1423/20-Y-234639	2023年8月7日	综合判定：合格	

283	GX-B1423/20-Y-234640	2023年8月7日	综合判定：合格	
284	GX-B1423/20-Y-234641	2023年8月7日	综合判定：合格	

285	GX-B1423/20-Y-234642	2023年8月7日	综合判定：合格		
286	GX-B1423/20-Y-234643	2023年8月7日	综合判定：合格		

287	GX-B1423/20-Y-234644	2023年8月7日	综合判定：合格		
288	GX-B1423/20-Y-234645	2023年8月7日	综合判定：合格		

289	GX-B1423/20-Y-234646	2023年8月7日	综合判定：合格	
290	GX-B1423/20-Y-234647	2023年8月7日	综合判定：合格	

291	GX-B1423/20-Y-234648	2023年8月7日	综合判定：合格	
292	GX-B1423/20-Y-234649	2023年8月7日	综合判定：合格	

293	GX-B1423/20-Y-234650	2023年8月7日	综合判定：合格	 <p>A yellow dump truck is shown from a side profile. A worker in a high-visibility vest and hard hat stands next to the front wheel. The truck has 'WELFARE' written on its side. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the image.</p>
294	GX-B1423/20-Y-234651	2023年8月7日	综合判定：合格	 <p>A yellow dump truck is shown from a side profile. Two workers in high-visibility vests and hard hats stand next to the front wheel. The truck has 'WELFARE' written on its side. A yellow timestamp '2023/7/16' is visible in the bottom right corner of the image.</p>

295	GX-B1423/20-Y-234652	2023年8月7日	综合判定：合格		
296	GX-B1423/20-Y-234653	2023年8月7日	综合判定：合格		

297	GX-B1423/20-Y-234654	2023年8月7日	综合判定：合格		
298	GX-B1423/20-Y-234655	2023年8月7日	综合判定：合格		

299	GX-B1423/20-Y-234656	2023年8月7日	综合判定：合格		
300	GX-B1423/20-Y-234657	2023年8月7日	综合判定：合格		

301	GX-B1423/20-Y-234658	2023年8月7日	综合判定：合格		
302	GX-B1423/20-Y-234659	2023年8月7日	综合判定：合格		

303	GX-B1423/20-Y-234660	2023年8月7日	综合判定：合格		
304	GX-B1423/20-Y-234661	2023年8月7日	综合判定：合格		

305	GX-B1423/20-Y-234662	2023年8月7日	综合判定：合格	
306	GX-B1423/20-Y-234663	2023年8月7日	综合判定：合格	

307	GX-B1423/20-Y-234664	2023年8月7日	综合判定：合格		
308	GX-B1423/20-Y-234665	2023年8月7日	综合判定：合格		

309	GX-B1521/20-Y-23398	2023年8月7日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	 A yellow excavator is shown on a construction site. Two workers in high-visibility vests are standing near the machine. The date stamp '2023/7/8' is visible in the bottom right corner of the photo.	
310	GX-B1521/20-Y-23399	2023年8月7日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2019 《土方机械 液压挖掘机 试验方法》，所检项目合格。	 A blue excavator is shown on a construction site. Two workers in high-visibility vests are standing near the machine. The date stamp '2023/7/8' is visible in the bottom right corner of the photo.	

311	GX-B1521/20-Y-23400	2023年8月7日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2020 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>		
312	GX-B1521/20-Y-23401	2023年8月7日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2021 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>		

313	GX-B1521/20-Y-23402	2023年8月7日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2022 《土方机械 液压挖掘机 试验方法》，所检项目合格。		
314	GX-B1521/20-Y-23403	2023年8月7日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2023 《土方机械 液压挖掘机 试验方法》，所检项目合格。		

315	GX-B1521/20-Y-23404	2023年8月7日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2024 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>		
316	GX-B1521/20-Y-23405	2023年8月7日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2025 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>		

317	GX-B1312/20-Y-23405~23411	2023年8月7日	本次共检电力变压器7台，7台电力变压器所检项目合格。	
318	GX-B1312/20-Y-23412~23413	2023年8月7日	本次共检电力变压器2台，2台电力变压器所检项目合格。	

319	GX-B1495/20-Y-231614~ 231633	2023年8月7日	本次共检高压开关柜20台，20台高压开关柜所检项目合格。	
320	GX-B1495/20-Y-231634~ 231635	2023年8月7日	本次共检电压互感器2组，2组电压互感器所检项目合格。	

321	GX-B1321/20-Y-23605~23615	2023年8月8日	本次共检验电力电缆11条，11条电力电缆所检项目合格。	
322	GX-B1517/20-Y-23023	2023年8月8日	综合判定：合格。	

323	GX-B1517/20-Y-23024	2023年8月8日	综合判定：合格。 。	 A photograph showing two workers in blue and grey uniforms and red hard hats standing next to a red rail vehicle on tracks. The vehicle is a small, orange-colored locomotive or engine. The background shows a building and a clear sky. A yellow timestamp '2023/7/14' is visible in the bottom right corner of the image.
324	GX-B1300/20-Y-23011	2023年8月8日	综合判定：合格。 。	 A photograph showing a worker in a grey uniform and red hard hat working on a large red industrial component. The worker is wearing a red hard hat and a grey uniform. The component is a large, red, cylindrical object with several blue bolts or fasteners. The background shows a building and a clear sky. A yellow timestamp '2023/7/17' is visible in the bottom right corner of the image.