

序号	报告编号	发布日期	结论	影像资料
378	GX-B1423/20-Y-234417	2023年8月9日	综合判定：合格	
379	GX-B1423/20-Y-234418	2023年8月9日	综合判定：合格	

380	GX-B1423/20-Y-234419	2023年8月9日	综合判定：合格	
381	GX-B1423/20-Y-234420	2023年8月9日	综合判定：合格	

382	GX-B1423/20-Y-234421	2023年8月9日	综合判定：合格	
383	GX-B1423/20-Y-234422	2023年8月9日	综合判定：合格	

384	GX-B1423/20-Y-234423	2023年8月9日	综合判定：合格	
385	GX-B1423/20-Y-234424	2023年8月9日	综合判定：合格	

386	GX-B1423/20-Y-234425	2023年8月9日	综合判定：合格	
387	GX-B1423/20-Y-234426	2023年8月9日	综合判定：合格	

388	GX-B1423/20-Y-234427	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a sandy, desert-like terrain under a blue sky with scattered clouds. Two workers in high-visibility vests and hard hats stand near the front of the truck. Various pieces of equipment, including a toolbox and bags, are laid out on the ground in front of the truck. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the image.
389	GX-B1423/20-Y-234428	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a sandy, desert-like terrain under a blue sky with scattered clouds. Two workers in high-visibility vests and hard hats stand near the front of the truck. Various pieces of equipment, including a toolbox and bags, are laid out on the ground in front of the truck. A yellow timestamp '2023/7/10' is visible in the bottom right corner of the image.

390	GX-B1423/20-Y-234429	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a sandy surface. Two workers in high-visibility vests and hard hats are standing near the front of the truck. Various pieces of equipment are laid out on the ground in front of the truck. A yellow date stamp '2023/7/10' is visible in the bottom right corner of the photo.
391	GX-B1423/20-Y-234430	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a sandy surface. Two workers in high-visibility vests and hard hats are standing near the front of the truck. Various pieces of equipment are laid out on the ground in front of the truck. A yellow date stamp '2023/7/10' is visible in the bottom right corner of the photo.

392	GX-B1423/20-Y-234431	2023年8月9日	综合判定：合格	
393	GX-B1423/20-Y-234432	2023年8月9日	综合判定：合格	

394	GX-B1423/20-Y-234433	2023年8月9日	综合判定：合格	
395	GX-B1423/20-Y-234478	2023年8月9日	综合判定：合格	

396	GX-B1423/20-Y-234479	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a sandy, open field under a blue sky with scattered clouds. Two workers in high-visibility vests are standing near the front of the truck. Various pieces of equipment and bags are laid out on the ground in front of the truck. A yellow date stamp '2023/7/11' is visible in the bottom right corner of the photo.
397	GX-B1423/20-Y-234480	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a sandy, open field under a blue sky with scattered clouds. Two workers in high-visibility vests are standing near the front of the truck. Various pieces of equipment and bags are laid out on the ground in front of the truck. A yellow date stamp '2023/7/11' is visible in the bottom right corner of the photo.

398	GX-B1423/20-Y-234481	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a sandy surface under a blue sky with scattered clouds. Two workers in high-visibility vests and hard hats stand near the front of the truck. The truck has the number '2' on its side. A date stamp '2023/7/11' is visible in the bottom right corner of the photo.
399	GX-B1423/20-Y-234482	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a sandy surface under a blue sky with scattered clouds. Two workers in high-visibility vests and hard hats stand near the front of the truck. The truck has the number '2' on its side. A date stamp '2023/7/11' is visible in the bottom right corner of the photo.

400	GX-B1423/20-Y-234483	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Three workers in high-visibility vests and hard hats are standing near the truck. The truck has the number '11770' on its side. A yellow timestamp '2023/7/11' is visible in the bottom right corner of the photo.
401	GX-B1423/20-Y-234484	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing near the truck. The truck has the number '1172440' on its side. A yellow timestamp '2023/7/11' is visible in the bottom right corner of the photo.

402	GX-B1423/20-Y-234485	2023年8月9日	综合判定：合格	
403	GX-B1423/20-Y-234486	2023年8月9日	综合判定：合格	

404	GX-B1423/20-Y-234487	2023年8月9日	综合判定：合格	
405	GX-B1423/20-Y-234488	2023年8月9日	综合判定：合格	

406	GX-B1423/20-Y-234489	2023年8月9日	综合判定：合格	
407	GX-B1423/20-Y-234490	2023年8月9日	综合判定：合格	

408	GX-B1423/20-Y-234491	2023年8月9日	综合判定：合格	
409	GX-B1423/20-Y-234492	2023年8月9日	综合判定：合格	

410	GX-B1423/20-Y-234493	2023年8月9日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats stand in front of the truck. The license plate on the side of the truck reads '2476'. A yellow timestamp '2023/7/11' is visible in the bottom right corner of the photo.</p>
411	GX-B1423/20-Y-234494	2023年8月9日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats stand in front of the truck. The license plate on the side of the truck reads '2482'. A yellow timestamp '2023/7/11' is visible in the bottom right corner of the photo.</p>

412	GX-B1423/20-Y-234495	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests stand near the front of the truck. The license plate on the side of the truck reads '2481'. A yellow timestamp '2023/7/11' is visible in the bottom right corner of the photo.
413	GX-B1423/20-Y-234496	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests stand near the front of the truck. The license plate on the side of the truck reads '2480'. A yellow timestamp '2023/7/11' is visible in the bottom right corner of the photo.

414	GX-B1423/20-Y-234497	2023年8月9日	综合判定：合格	
415	GX-B1423/20-Y-234498	2023年8月9日	综合判定：合格	

416	GX-B1423/20-Y-234499	2023年8月9日	综合判定：合格	 A yellow dump truck with the number 2478 on its side is parked on a dirt surface. Two workers in high-visibility vests are standing in front of the truck. The date 2023/7/11 is visible in the bottom right corner of the photo.
417	GX-B1423/20-Y-234500	2023年8月9日	综合判定：合格	 A yellow dump truck with the number 2485 on its side is parked on a dirt surface. Two workers in high-visibility vests are standing in front of the truck. The date 2023/7/11 is visible in the bottom right corner of the photo.

418	GX-B1423/20-Y-234501	2023年8月9日	综合判定：合格	 A yellow dump truck with the number '2487' on its side is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/7/11' is visible in the bottom right corner of the image.
419	GX-B1423/20-Y-234502	2023年8月9日	综合判定：合格	 A yellow dump truck with the number '2489' on its side is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/7/11' is visible in the bottom right corner of the image.

420	GX-B1423/20-Y-234503	2023年8月9日	综合判定：合格	
421	GX-B1423/20-Y-234262	2023年8月9日	综合判定：合格	

422	GX-B1423/20-Y-234263	2023年8月9日	综合判定：合格	 A yellow XCMG MX3130 dump truck is shown from a side-rear perspective. The truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing near the front wheel. The truck has "XCMG" and "MX3130" visible on its side. A yellow timestamp "2023/7/23" is in the bottom right corner.
423	GX-B1423/20-Y-234264	2023年8月9日	综合判定：合格	 A yellow XCMG MX3130 dump truck is shown from a side-rear perspective. The truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing near the front wheel. A third worker in a red shirt is partially visible on the right. The truck has "XCMG" and "MX3130" visible on its side. A yellow timestamp "2023/7/23" is in the bottom right corner.

424	GX-B1423/20-Y-234265	2023年8月9日	综合判定：合格	
425	GX-B1423/20-Y-234266	2023年8月9日	综合判定：合格	

426	GX-B1423/20-Y-234267	2023年8月9日	综合判定：合格	
427	GX-B1423/20-Y-234268	2023年8月9日	综合判定：合格	

428	GX-B1423/20-Y-234269	2023年8月9日	综合判定：合格	 A yellow XCMG MX3155 dump truck is shown from a side-rear perspective. The truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats are standing near the rear of the truck. A yellow timestamp '2023/7/23' is visible in the bottom right corner of the image.
429	GX-B1423/20-Y-234270	2023年8月9日	综合判定：合格	 A yellow XCMG MX3155 dump truck is shown from a side-rear perspective. The truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats are standing near the rear of the truck. A yellow timestamp '2023/7/23' is visible in the bottom right corner of the image.

430	GX-B1423/20-Y-234271	2023年8月9日	综合判定：合格	 A yellow XGMA MX3155 dump truck is shown from a front-three-quarter view. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The truck has 'XGMA' and 'MX3155' visible on its side. A yellow date stamp '2023/7/23' is in the bottom right corner.
431	GX-B1423/20-Y-234272	2023年8月9日	综合判定：合格	 A yellow XGMA MX3157 dump truck is shown from a rear-three-quarter view. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The truck has 'XGMA' and 'MX3157' visible on its side. A yellow date stamp '2023/7/23' is in the bottom right corner.

432	GX-B1423/20-Y-234273	2023年8月9日	综合判定：合格	 A yellow XG105 dump truck is shown from a front-three-quarter view. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The truck has 'XG105' and 'BEAT' visible on its side. A yellow timestamp '2023/7/23' is in the bottom right corner.
433	GX-B1423/20-Y-234274	2023年8月9日	综合判定：合格	 A yellow XG105 dump truck is shown from a rear-three-quarter view. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The truck has 'XG105' and 'BEAT' visible on its side. A yellow timestamp '2023/7/23' is in the bottom right corner.

434	GX-B1423/20-Y-234275	2023年8月9日	综合判定：合格	
435	GX-B1423/20-Y-234276	2023年8月9日	综合判定：合格	

436	GX-B1423/20-Y-234277	2023年8月9日	综合判定：合格	 A yellow XCMG MX3153 dump truck is shown from a side-rear perspective. The truck has 'MX3153' and 'XCMG' branding. Two workers in high-visibility vests and hard hats stand near the front wheel. A yellow timestamp '2023/7/23' is visible in the bottom right corner of the image.
437	GX-B1423/20-Y-234278	2023年8月9日	综合判定：合格	 A yellow XCMG MX3154 dump truck is shown from a side-rear perspective. The truck has 'MX3154' and 'XCMG' branding. Two workers in high-visibility vests and hard hats stand near the front wheel. A yellow timestamp '2023/7/24' is visible in the bottom right corner of the image.

438	GX-B1423/20-Y-234279	2023年8月9日	综合判定：合格	 A yellow dump truck, model MX3150, is shown from a side-rear perspective. Two workers in high-visibility vests and hard hats stand in front of the truck for scale. The truck is parked on a dirt surface under a clear blue sky. A yellow timestamp '2023/7/24' is visible in the bottom right corner of the image.
439	GX-B1423/20-Y-234280	2023年8月9日	综合判定：合格	 A yellow dump truck, model MX3130, is shown from a side-rear perspective. Two workers in high-visibility vests and hard hats stand in front of the truck for scale. The truck is parked on a dirt surface under a clear blue sky. A yellow timestamp '2023/7/24' is visible in the bottom right corner of the image.

440	GX-B1423/20-Y-234281	2023年8月9日	综合判定：合格	 A yellow XG10S dump truck with license plate MX3137 is shown from a side-rear perspective. Two workers in high-visibility vests and hard hats stand near the front wheel. The truck is parked on a dirt surface under a clear blue sky. A yellow timestamp '2023/7/24' is visible in the bottom right corner of the image.
441	GX-B1423/20-Y-234282	2023年8月9日	综合判定：合格	 A yellow XG10S dump truck with license plate MX3156 is shown from a side-rear perspective. Two workers in high-visibility vests and hard hats stand near the front wheel. The truck is parked on a dirt surface under a clear blue sky. A yellow timestamp '2023/7/24' is visible in the bottom right corner of the image.

442	GX-B1423/20-Y-234283	2023年8月9日	综合判定：合格	
443	GX-B1423/20-Y-234284	2023年8月9日	综合判定：合格	

444	GX-B1423/20-Y-234285	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and high-visibility vests are standing in front of the truck. A yellow date stamp '2023/7/24' is visible in the bottom right corner of the image.
445	GX-B1423/20-Y-234286	2023年8月9日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and high-visibility vests are standing in front of the truck. A yellow date stamp '2023/7/24' is visible in the bottom right corner of the image.

446	GX-B1423/20-Y-234287	2023年8月9日	综合判定：合格	
447	GX-B1423/20-Y-234288	2023年8月9日	综合判定：合格	

448	GX-B1423/20-Y-234289	2023年8月9日	综合判定：合格	 A yellow MT96L dump truck is shown from a side-rear perspective. The license plate reads MX3419. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/7/24' is visible in the bottom right corner of the photo.
449	GX-B1423/20-Y-234290	2023年8月9日	综合判定：合格	 A yellow MT96L dump truck is shown from a side-front perspective. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/7/24' is visible in the bottom right corner of the photo.

450	GX-B1423/20-Y-234291	2023年8月9日	综合判定：合格	
451	GX-B1423/20-Y-234292	2023年8月9日	综合判定：合格	

452	GX-B1423/20-Y-234293	2023年8月9日	综合判定：合格	
453	GX-B1423/20-Y-234294	2023年8月9日	综合判定：合格	

454	GX-B1423/20-Y-234295	2023年8月9日	综合判定：合格	
455	GX-B1423/20-Y-234296	2023年8月9日	综合判定：合格	

456	GX-B1423/20-Y-234297	2023年8月9日	综合判定：合格	 <p>A yellow XG105 dump truck is shown from a side-rear perspective. The truck has the license plate number '3223' painted on its side. Two workers wearing high-visibility vests and hard hats are standing in front of the truck. The background is a clear blue sky and a dirt ground. A yellow timestamp '2023/7/26' is visible in the bottom right corner of the image.</p>
457	GX-B1423/20-Y-234298	2023年8月9日	综合判定：合格	 <p>A yellow XG105 dump truck is shown from a side-rear perspective. The truck has the license plate number '3422' painted on its side. Two workers wearing high-visibility vests and hard hats are standing in front of the truck. The background is a clear blue sky and a dirt ground. A yellow timestamp '2023/7/26' is visible in the bottom right corner of the image.</p>

458	GX-B1423/20-Y-234299	2023年8月9日	综合判定：合格	 A yellow dump truck is shown from a front-three-quarter view. The license plate on the side of the truck reads "3S39". Two workers in high-visibility vests and hard hats are standing near the front of the truck. A yellow timestamp "2023/7/25" is visible in the bottom right corner of the image.
459	GX-B1423/20-Y-234300	2023年8月9日	综合判定：合格	 A yellow dump truck is shown from a rear-three-quarter view. The license plate on the side of the truck reads "3212". Two workers in high-visibility vests and hard hats are standing near the rear of the truck. A yellow timestamp "2023/7/25" is visible in the bottom right corner of the image.

460	GX-B1423/20-Y-234301	2023年8月9日	综合判定：合格	
461	GX-B1423/20-Y-234302	2023年8月9日	综合判定：合格	

462	GX-B1423/20-Y-234303	2023年8月9日	综合判定：合格	
463	GX-B1423/20-Y-234304	2023年8月9日	综合判定：合格	

464	GX-B1423/20-Y-234305	2023年8月9日	综合判定：合格	
465	GX-B1423/20-Y-234306	2023年8月9日	综合判定：合格	

466	GX-B1423/20-Y-234307	2023年8月9日	综合判定：合格	
467	GX-B1423/20-Y-234308	2023年8月9日	综合判定：合格	

468	GX-B1423/20-Y-234309	2023年8月9日	综合判定：合格	
469	GX-B1423/20-Y-234310	2023年8月9日	综合判定：合格	

470	GX-B1423/20-Y-234311	2023年8月9日	综合判定：合格	
471	GX-B1423/20-Y-234312	2023年8月9日	综合判定：合格	

472	GX-B1423/20-Y-234313	2023年8月9日	综合判定：合格	
473	GX-B1423/20-Y-234314	2023年8月9日	综合判定：合格	

474	GX-B1423/20-Y-234315	2023年8月9日	综合判定：合格	
475	GX-B1423/20-Y-234316	2023年8月9日	综合判定：合格	

476	GX-B1423/20-Y-234317	2023年8月9日	综合判定：合格	
477	GX-B1423/20-Y-234318	2023年8月9日	综合判定：合格	

478	GX-B1423/20-Y-234319	2023年8月9日	综合判定：合格	
479	GX-B1423/20-Y-234320	2023年8月9日	综合判定：合格	

480	GX-B1423/20-Y-234321	2023年8月9日	综合判定：合格	 A yellow XGIDF MX3193 dump truck is shown from a side-rear perspective. The truck has the number '2813' painted on its side. Two workers in high-visibility vests and hard hats are standing in front of the truck. A yellow timestamp '2023/7/26' is visible in the bottom right corner of the photo.
481	GX-B1423/20-Y-234322	2023年8月9日	综合判定：合格	 A yellow XGIDF MX3199 dump truck is shown from a side-rear perspective. The truck has the number '9913' painted on its side. Two workers in high-visibility vests and hard hats are standing in front of the truck. A yellow timestamp '2023/7/26' is visible in the bottom right corner of the photo.

482	GX-B1423/20-Y-234323	2023年8月9日	综合判定：合格	 <p>A yellow dump truck with the identification number 3227 on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/7/25' is visible in the bottom right corner of the photo.</p>
483	GX-B1423/20-Y-234324	2023年8月9日	综合判定：合格	 <p>A yellow dump truck with the identification number 32191 on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/7/26' is visible in the bottom right corner of the photo.</p>

484	GX-B1423/20-Y-234325	2023年8月9日	综合判定：合格	 A yellow XCMG dump truck is shown from a side profile. The license plate on the side of the truck reads '5223'. Two workers in high-visibility vests and hard hats are standing next to the truck. A yellow date stamp '2023/7/25' is visible in the bottom right corner of the photo.
485	GX-B1423/20-Y-234326	2023年8月9日	综合判定：合格	 A yellow XCMG dump truck is shown from a side profile. The license plate on the side of the truck reads '9223'. Two workers in high-visibility vests and hard hats are standing next to the truck. A yellow date stamp '2023/7/27' is visible in the bottom right corner of the photo.

486	GX-B1423/20-Y-234327	2023年8月9日	综合判定：合格	 <p>A yellow XCMG dump truck with identification number 0023 on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/7/27' is visible in the bottom right corner of the image.</p>
487	GX-B1423/20-Y-234328	2023年8月9日	综合判定：合格	 <p>A yellow XCMG dump truck with identification number 2185 on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/7/27' is visible in the bottom right corner of the image.</p>

488	GX-B1423/20-Y-234329	2023年8月9日	综合判定：合格	 A yellow XCMG 3206 dump truck is shown from a side-rear perspective. The truck has 'XCMG' and '3206' written on its side. Two workers in high-visibility vests and hard hats are standing in front of the truck. A yellow timestamp '2023/7/27' is visible in the bottom right corner of the image.
489	GX-B1423/20-Y-234330	2023年8月9日	综合判定：合格	 A yellow XCMG 3192 dump truck is shown from a side-rear perspective. The truck has 'XCMG' and '3192' written on its side. Two workers in high-visibility vests and hard hats are standing in front of the truck. A yellow timestamp '2023/7/27' is visible in the bottom right corner of the image.

490	GX-B1423/20-Y-234331	2023年8月9日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. The license plate on the side of the truck reads "5123". Two workers in high-visibility vests and hard hats are standing next to the truck. A yellow timestamp "2023/7/27" is visible in the bottom right corner of the image.
491	GX-B1423/20-Y-234332	2023年8月9日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. The license plate on the side of the truck reads "1323". Two workers in high-visibility vests and hard hats are standing next to the truck. A yellow timestamp "2023/7/27" is visible in the bottom right corner of the image.

492	GX-B1423/20-Y-234333	2023年8月9日	综合判定：合格	
493	GX-B1423/20-Y-234334	2023年8月9日	综合判定：合格	

494	GX-B1423/20-Y-234335	2023年8月9日	综合判定：合格	
495	GX-B1423/20-Y-234336	2023年8月9日	综合判定：合格	

496	GX-B1423/20-Y-234337	2023年8月9日	综合判定：合格	
497	GX-B1423/20-Y-234338	2023年8月9日	综合判定：合格	

498	GX-B1423/20-Y-234339	2023年8月9日	综合判定：合格	
499	GX-B1423/20-Y-234340	2023年8月9日	综合判定：合格	

500	GX-B1423/20-Y-234341	2023年8月9日	综合判定：合格	
501	GX-B1423/20-Y-234342	2023年8月9日	综合判定：合格	

502	GX-B1423/20-Y-234343	2023年8月9日	综合判定：合格	
-----	----------------------	-----------	---------	---