

序号	报告编号	发布日期	结论	影像资料
100	GX-B1517/20-3-23022	2023年8月11日	综合判定：合格。	 A man in a blue uniform is standing next to a red rail vehicle on a track. He is looking down at something in his hands. The vehicle has a red body and a black roof. The date 2023/07/12 is visible in the bottom right corner of the image.
101	GX-B1517/20-3-23023	2023年8月11日	综合判定：合格。	 A man in a blue uniform is crouching next to a red rail vehicle. He is looking at something on the side of the vehicle. The vehicle has a red body and a black roof. The date 2023/07/12 is visible in the bottom right corner of the image.
102	GX-B1517/20-3-23024	2023年8月11日	综合判定：合格。	 A man in a blue uniform is standing next to a red rail vehicle on a track. He is looking down at something in his hands. The vehicle has a red body and a black roof. The date 2023/07/12 is visible in the bottom right corner of the image.

103	GX-B1517/20-3-23025	2023年8月11日	综合判定：合格。	
104	GX-B1517/20-3-23026	2023年8月11日	综合判定：合格。	
105	GX-B1517/20-3-23027	2023年8月11日	综合判定：合格。	

106	GX-B1517/20-3-23028	2023年8月11日	综合判定：合格。	
107	GX-B1517/20-3-23029	2023年8月11日	综合判定：合格。	
108	GX-B1517/20-3-23030	2023年8月11日	综合判定：合格。	

109	GX-B1517/20-3-23031	2023年8月11日	综合判定：合格。	
110	GX-B1517/20-3-23032	2023年8月11日	综合判定：合格。	
111	GX-B1517/20-3-23033	2023年8月11日	综合判定：合格。	


112	GX-B1517/20-3-23034	2023年8月11日	综合判定：合格。	 2023/07/13
113	GX-B1517/20-3-23035	2023年8月11日	综合判定：合格。	 2023/07/13
114	GX-B1517/20-3-23036	2023年8月11日	综合判定：合格。	 2023/07/13

115	GX-B1352/21-3-23395~23396	2023年8月11日	本次共检矿用防爆低压交流真空馈电开关 2台, 2台所检项目合格。	
116	GX-B1495/20-3-234603	2023年8月11日	所检项目合格。	
117	GX-B1323/21-3-23285~23286	2023年8月15日	本次共检三相交流电动机2台, 2台三相交流电动机所检项目合格。	

118	GX-B1310/21-3-23130	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
119	GX-B1310/21-3-23131	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
120	GX-B1310/21-3-23132	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	


121	GX-B1310/21-3-23133	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
122	GX-B1310/21-3-23134	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
123	GX-B1310/21-3-23135	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

124	GX-B1310/21-3-23136	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
125	GX-B1310/21-3-23137	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
126	GX-B1310/21-3-23138	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

127	GX-B1310/21-3-23139	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
128	GX-B1310/21-3-23140	2023年8月13日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
129	GX-B1321/20-3-231696~231698	2023年8月14日	本次共检电力电缆3条，3条电力电缆所检项目合格。	



130	GX-B1329/21-3-23229 ~ 23242	2023年8月14日	本次共检氧化锌避雷器 14组，14组氧化锌避雷器所 检项目合格	
131	GX-B1307/20-3-23025	2023年8月14日	综合判定：合格	
132	GX-B1307/20-3-23026	2023年8月14日	综合判定：合格	


133	GX-B1328/20-3-23170	2023. 8. 16	本次共检绝缘手套2只，2只绝缘手套合格。		
134	GX-B1328/20-3-23171	2023. 8. 16	本次共检绝缘鞋2只，2只绝缘鞋合格。		
135	GX-B1328/20-3-23172	2023. 8. 16	合格。		

136	GX-B1328/20-3-23173	2023. 8. 16	合格。	
137	GX-B1328/20-3-23174	2023. 8. 16	合格。	
138	GX-B1548/20-3-23008	2023年8月17日	所检项目合格。	

139	GX-B1548/20-3-23009	2023年8月17日	所检项目合格。		
140	GX-B1311/21-3-23005	2023. 8. 17	Φ377×10无缝钢管实测最小壁厚为10.17mm，Φ377×18无缝钢管实测最小壁厚为17.58mm。		
141	GX-B1311/21-3-23006	2023. 8. 17	Φ377×10无缝钢管实测最小壁厚为10.12mm，Φ377×18无缝钢管实测最小壁厚为17.49mm。		

142	GX-B1311/21-3-23007	2023. 8. 17	250×250×13mm方形空心钢 罐道实测最小壁厚为 12. 73mm。			
143	GX-B1311/21-3-23008	2023. 8. 17	250×250×13mm方形空心钢 罐道实测最小壁厚为 12. 48mm。			
144	GX-B1311/21-3-23009	2023. 8. 17	220×220×12mm方形空心钢 罐道实测最小壁厚为 11. 47mm。			

145	GX-B1311/21-3-23010	2023. 8. 17	220×220×12mm方形空心钢罐道实测最小壁厚为11.46mm。			
146	GX-B1311/21-3-23011	2023. 8. 17	Φ377×10无缝钢管实测最小壁厚为10.18mm，Φ377×18无缝钢管实测最小壁厚为17.81mm。			
147	GX-B1311/21-3-23012	2023. 8. 17	Φ377×10无缝钢管实测最小壁厚为10.27mm，Φ377×18无缝钢管实测最小壁厚为18.45mm。			

148	GX-B1311/21-3-23013	2023. 8. 17	Φ 273×9无缝钢管实测最小壁厚为10.06mm。			
149	GX-B1311/21-3-23014	2023. 8. 17	Φ 168×7无缝钢管实测最小壁厚为8.28mm。			
150	GX-B1311/21-3-23015	2023. 8. 17	Φ 219×10无缝钢管实测最小壁厚为9.48mm。			

151	GX-B1311/21-3-23016	2023. 8. 17	220×220×16mm方形空心钢 罐道实测最小壁厚为 15.48mm。			
152	GX-B1311/21-3-23017	2023. 8. 17	220×220×16mm方形空心钢 罐道实测最小壁厚为 15.44mm。			
153	GX-B1311/21-3-23018	2023. 8. 17	220×220×16mm方形空心钢 罐道实测最小壁厚为 15.24mm。			

154	GX-B1311/21-3-23019	2023. 8. 17	220×220×16mm方形空心钢 罐道实测最小壁厚为 15.12mm。			
155	GX-B1311/21-3-23020	2023. 8. 17	Φ377×9无缝钢管实测最小 壁厚为6.11mm。			
156	GX-B1311/21-3-23021	2023. 8. 17	Φ273×7无缝钢管实测最小 壁厚为6.49mm。			

157	GX-B1311/21-3-23022	2023. 8. 17	220×220×16mm方形空心钢 罐道实测最小壁厚为 15.87mm。			
158	GX-B1311/21-3-23023	2023. 8. 17	220×220×16mm方形空心钢 罐道实测最小壁厚为 16.11mm。			
159	GX-B1311/21-3-23024	2023. 8. 17	220×220×16mm方形空心钢 罐道实测最小壁厚为 15.87mm。			

160	GX-B1311/21-3-23025	2023. 8. 17	220×220×16mm方形空心钢 罐道实测最小壁厚为 15.81mm。	
161	GX-B1310/21-3-23105	2023. 8. 17	符合标准要求。	
162	GX-B1310/21-3-23106	2023. 8. 17	符合标准要求。	

163	GX-B1310/21-3-23107	2023. 8. 17	符合标准要求。		
164	GX-B1310/21-3-23108	2023. 8. 17	符合标准要求。		
165	GX-B1310/21-3-23109	2023. 8. 17	符合标准要求。		

166	GX-B1310/21-3-23110	2023. 8. 17	符合标准要求。			
167	GX-B1310/21-3-23111	2023. 8. 17	符合标准要求。			
168	GX-B1310/21-3-23112	2023. 8. 17	符合标准要求。			


169	GX-B1310/21-3-23113	2023. 8. 17	符合标准要求。			
170	GX-B1310/21-3-23162	2023. 8. 17	符合标准要求。			
171	GX-B1427/21-3-23039	2023. 8. 17	符合标准要求。			

172	GX-B1328/20-3-23179	2023年8月15日	本次共检绝缘手套70只，70只绝缘手套合格。	
173	GX-B1328/20-3-23180	2023年8月15日	本次共检绝缘鞋66只，66只绝缘鞋合格。	
174	GX-B1328/20-3-23181	2023年8月15日	本次共检验电器23支，23支验电器所检项目合格。	

175	GX-B1328/20-3-23182	2023年8月15日	本次共检绝缘胶垫109件， 109件绝缘胶垫合格。	
176	GX-B1328/20-3-23183	2023年8月15日	本次共检携带式接地和接地 短路装置6套，6套携带式接 地和接地短路装置合格。	
177	GX-B1328/20-3-23184	2023年8月15日	本次共检绝缘杆6套，6套绝 缘杆合格。	

178	GX-B1310/21-3-23150	2023. 8. 17	符合标准要求	 A worker in a blue uniform and helmet is operating a large industrial machine with a red light. The date 2023.7.30 is visible in the bottom right corner of the image.
179	GX-B1310/21-3-23151	2023. 8. 17	符合标准要求	 A worker in a blue uniform and helmet is operating a large industrial machine with a red light. The date 2023.7.30 is visible in the bottom right corner of the image.
180	GX-B1310/21-3-23152	2023. 8. 17	符合标准要求	 A worker in a blue uniform and helmet is operating a large industrial machine with a red light. The date 2023.7.30 is visible in the bottom right corner of the image.

181	GX-B1310/21-3-23153	2023. 8. 17	符合标准要求	 A worker in a blue uniform and hard hat is operating a large industrial machine, possibly a pump or motor, in an industrial setting. The date stamp '2023.7.30' is visible in the bottom right corner of the image.	
182	GX-B1310/21-3-23154	2023. 8. 17	符合标准要求	 A worker in a blue uniform and yellow boots is operating a large industrial machine, possibly a pump or motor, in an industrial setting. The date stamp '2023.7.30' is visible in the bottom right corner of the image.	
183	GX-B1310/21-3-23155	2023. 8. 17	符合标准要求	 A worker in a blue uniform and yellow boots is operating a large industrial machine, possibly a pump or motor, in an industrial setting. The date stamp '2023.7.30' is visible in the bottom right corner of the image.	


184	GX-B1310/21-3-23156	2023. 8. 17	符合标准要求			
185	GX-B1427/21-3-23037	2023. 8. 17	符合标准要求			
186	GX-B1350/21-3-23024	2023. 8. 11	所检项目合格。			

187	GX-B1350/21-3-23018	2023. 8. 9	所检项目合格。	
188	GX-B1350/21-3-23019	2023. 8. 9	所检项目合格。	
189	GX-B1350/21-3-23020	2023. 8. 9	所检项目合格。	

190	GX-B1350/21-3-23021	2023. 8. 9	所检项目合格。	
191	GX-B1350/21-3-23022	2023. 8. 9	所检项目合格。	
192	GX-B1350/21-3-23023	2023. 8. 9	所检项目合格。	

193	GX-B1495/20-3-234498 ~ 234515	2023年8月17日	本次共检电压互感器18组， 18组电压互感器所检项目合格。		
194	GX-B1495/20-3-234516 ~ 234531	2023年8月17日	本次共检电压互感器16组， 16组电压互感器所检项目合格。		
195	GX-B1495/20-3-234532 ~ 234567	2023年8月17日	本次共检电压互感器36组， 36组电压互感器所检项目合格。		

196	GX-B1495/20-3-234568 ~ 234586	2023年8月17日	本次共检电压互感器19组， 19组电压互感器所检项目合格。			
197	GX-B1495/20-3-234587 ~ 234602	2023年8月17日	本次共检电压互感器16组， 16组电压互感器所检项目合格。			
198	GX-B1336/22-3-23117 ~ 23132	2023年8月17日	本次共检母线16段，16段所 检项目合格。			

199	GX-B1336/22-3-23133 ~ 23136	2023年8月17日	本次共检母线4段，4段所检项目合格。	
200	GX-B1336/22-3-23137 ~ 23145	2023年8月17日	本次共检母线9段，9段所检项目合格。	
201	GX-B1336/22-3-23146 ~ 23157	2023年8月17日	本次共检母线12段，12段所检项目合格。	

202	GX-B1336/22-3-23158 ~ 23165	2023年8月17日	本次共检母线8段，8段所检项目合格。	
203	GX-B1336/22-3-23166 ~ 23177	2023年8月17日	本次共检母线12段，12段所检项目合格。	
204	GX-B1495/20-3-234730 ~ 234740	2023年8月17日	本次共检电流互感器11只，11只电流互感器所检项目合格。	

205	GX-B1495/20-3-234741 ~ 234769	2023年8月17日	本次共检电流互感器29只， 29只电流互感器所检项目合格。	 2023.06.04
206	GX-B1495/20-3-234770 ~ 234783	2023年8月17日	本次共检电流互感器14只， 14只电流互感器所检项目合格。	 2023.06.04
207	GX-B1495/20-3-234784 ~ 234801	2023年8月17日	本次共检电流互感器18只， 18只电流互感器所检项目合格。	 2023.06.05


208	GX-B1495/20-3-234802 ~ 234819	2023年8月17日	本次共检电流互感器18只， 18只电流互感器所检项目合格。	
209	GX-B1495/20-3-234820 ~ 234859	2023年8月17日	本次共检电流互感器40只， 40只电流互感器所检项目合格。	
210	GX-B1495/20-3-234604 ~ 234648	2023年8月17日	本次共检电流互感器45只， 45只电流互感器所检项目合格。	

211	GX-B1495/20-3-234649 ~ 234654	2023年8月17日	本次共检电流互感器6只，6只电流互感器所检项目合格。		
212	GX-B1495/20-3-234655 ~ 234695	2023年8月17日	本次共检电流互感器41只，41只电流互感器所检项目合格。		
213	GX-B1495/20-3-234696 ~ 234701	2023年8月17日	本次共检电流互感器6只，6只电流互感器所检项目合格。		

214	GX-B1495/20-3-234702 ~ 234729	2023年8月17日	本次共检电流互感器28只， 28只电流互感器所检项目合格。	
215	GX-B1495/20-3-234228~234249	2023年8月18日	本次共检电流互感器22只， 22只电流互感器所检项目合格。	
216	GX-B1495/20-3-234250~234273	2023年8月18日	本次共检电流互感器24只， 24只电流互感器所检项目合格。	

217	GX-B1495/20-3-234274~234295	2023年8月18日	本次共检电流互感器22只， 22只电流互感器所检项目合格。	 2023.05.19
218	GX-B1495/20-3-234296~234317	2023年8月18日	本次共检电流互感器22只， 22只电流互感器所检项目合格。	 2023.05.19
219	GX-B1495/20-3-234326~234353	2023年8月18日	本次共检电流互感器28只， 28只电流互感器所检项目合格。	 2023.05.20

220	GX-B1495/20-3-234354~234377	2023年8月18日	本次共检电流互感器24只， 24只电流互感器所检项目合格。	
221	GX-B1495/20-3-234378~234433	2023年8月18日	本次共检电流互感器56只， 56只电流互感器所检项目合格。	
222	GX-B1495/20-3-234434~234469	2023年8月18日	本次共检电流互感器36只， 36只电流互感器所检项目合格。	

223	GX-B1495/20-3-234470~234497	2023年8月18日	本次共检电流互感器28只， 28只电流互感器所检项目合格。	
224	GX-B1495/20-3-235201~235256	2023. 8. 21	本次共检电流互感器56只， 56只电流互感器所检项目合格。	
225	GX-B1495/20-3-235421~235448	2023. 8. 21	本次共检电压互感器28组， 28组电压互感器所检项目合格。	

226	GX-B1495/20-3-235257~235276	2023. 8. 21	本次共检电流互感器20只， 20只电流互感器所检项目合格。	
227	GX-B1495/20-3-235449~235456	2023. 8. 21	本次共检电压互感器8组，8 组电压互感器所检项目合格。 。	
228	GX-B1495/20-3-235277~235292	2023. 8. 21	本次共检电流互感器16只， 16只电流互感器所检项目合格。	

229	GX-B1495/20-3-235457~235468	2023. 8. 21	本次共检电压互感器12组， 12组电压互感器所检项目合格。	
230	GX-B1495/20-3-235293~235305	2023. 8. 21	本次共检电流互感器13只， 13只电流互感器所检项目合格。	
231	GX-B1495/20-3-235306~235324	2023. 8. 21	本次共检电流互感器19只， 19只电流互感器所检项目合格。	

232	GX-B1495/20-3-235325~235377	2023. 8. 21	本次共检电流互感器53只，53只电流互感器所检项目合格。	
233	GX-B1495/20-3-235469~235477	2023. 8. 21	本次共检电压互感器9组，9组电压互感器所检项目合格。	
234	GX-B1495/20-3-235378~235420	2023. 8. 21	本次共检电流互感器43只，43只电流互感器所检项目合格。	

235	GX-B1495/20-3-234981~234998	2023. 8. 21	本次共检电流互感器18只， 18只电流互感器所检项目合格。	
236	GX-B1495/20-3-235019~235026	2023. 8. 21	本次共检电压互感器8组，8 组电压互感器所检项目合格。 。	
237	GX-B1495/20-3-234885~234917	2023. 8. 21	本次共检电流互感器33只， 33只电流互感器所检项目合格。	

238	GX-B1495/20-3-234999~235018	2023. 8. 21	本次共检电压互感器20组， 20组电压互感器所检项目合格。	
239	GX-B1495/20-3-234871~234884	2023. 8. 21	本次共检电流互感器14只， 14只电流互感器所检项目合格。	
240	GX-B1495/20-3-234963~234980	2023. 8. 21	本次共检电流互感器18只， 18只电流互感器所检项目合格。	

241	GX-B1495/20-3-234860~234870	2023. 8. 21	本次共检电流互感器11只， 11只电流互感器所检项目合格。	
242	GX-B1495/20-3-234918~234962	2023. 8. 21	本次共检电流互感器45只， 45只电流互感器所检项目合格。	
243	GX-B1321/20-3-231624~231631	2023年8月15日	本次共检电力电缆8条，8条 电力电缆所检项目合格。	

244	GX-B1312/20-3-23633~23634	2023. 8. 15	本次共检电力变压器2台，2台电力变压器所检项目合格。	
245	GX-B1328/20-3-23175	2023年8月15日	本次共检绝缘手套2只，2只绝缘手套合格。	
246	GX-B1328/20-3-23176	2023年8月15日	本次共检绝缘鞋2只，2只绝缘鞋合格。	
247	GX-B1328/20-3-23177	2023年8月15日	本次共检高压验电器1支，所检项目合格。	
248	GX-B1328/20-3-23178	2023年8月15日	合格。	