

序号	报告编号	发布日期	结论	影像资料
27	GX-B1310/21-4-23104	2023. 9. 6	符合标准要求	
28	GX-B1310/21-4-23105	2023. 9. 6	符合标准要求	
29	GX-B1310/21-4-23106	2023. 9. 6	符合标准要求	

30	GX-B1310/21-4-23107	2023. 9. 6	符合标准要求	
31	GX-B1310/21-4-23108	2023. 9. 6	符合标准要求	
32	GX-B1310/21-4-23109	2023. 9. 6	符合标准要求	

33	GX-B1310/21-4-23110	2023. 9. 6	符合标准要求	
34	GX-B1310/21-4-23111	2023. 9. 6	符合标准要求	
35	GX-B1310/21-4-23112	2023. 9. 6	符合标准要求	

36	GX-B1310/21-4-23113	2023. 9. 6	符合标准要求	
37	GX-B1310/21-4-23114	2023. 9. 6	符合标准要求	
38	GX-B1310/21-4-23115	2023. 9. 6	符合标准要求	

39	GX-B1310/21-4-23116	2023. 9. 6	符合标准要求	
40	GX-B1310/21-4-23117	2023. 9. 6	符合标准要求	
41	GX-B1310/21-4-23118	2023. 9. 6	符合标准要求	

42	GX-B1313/21-4-23050	2023. 9. 11	本次共检电力变压器1台，1台电力变压器所检项目合格	
43	GX-B1380/20-4-23011	2023. 9. 11	所检项目合格。	
44	GX-B1535/21-4-23001	2023. 9. 11	所检项目合格。	

45	GX-B1352/21-4-23896~23903	2023. 9. 12	本次共检矿用防爆低压交流真空馈电开关8台, 8台所检项目合格。	
46	GX-B1423/20-2-23051	2023. 9. 13	综合判定：合格	
47	GX-B1423/20-2-23052	2023. 9. 13	综合判定：合格	

48	GX-B1423/20-2-23053	2023. 9. 13	综合判定：合格	
49	GX-B1423/20-2-23054	2023. 9. 13	综合判定：合格	
50	GX-B1423/20-2-23055	2023. 9. 13	综合判定：合格	

51	GX-B1423/20-2-23056	2023. 9. 13	综合判定：合格	 <p>2023/8/29</p>
52	GX-B1423/20-2-23057	2023. 9. 13	综合判定：合格	 <p>2023/8/29</p>
53	GX-B1423/20-2-23058	2023. 9. 13	综合判定：合格	 <p>2023/8/29</p>

54	GX-B1423/20-2-23059	2023. 9. 13	综合判定：合格	
55	GX-B1423/20-2-23060	2023. 9. 13	综合判定：合格	
56	GX-B1423/20-2-23061	2023. 9. 13	综合判定：合格	

57	GX-B1423/20-2-23062	2023. 9. 13	综合判定：合格	 A photograph showing a person wearing a white hard hat and a light-colored uniform sitting in the driver's seat of a yellow vehicle, possibly a forklift or a similar industrial machine. The person is looking forward, and the steering wheel is visible. A timestamp "2023.8.30" is visible in the bottom right corner of the image.
58	GX-B1423/20-2-23063	2023. 9. 13	综合判定：合格	 A photograph showing a person wearing a white hard hat and a light-colored uniform sitting in the driver's seat of a yellow vehicle, similar to the one in the first row. The person is looking forward, and the steering wheel is visible. A timestamp "2023.8.30" is visible in the bottom right corner of the image.
59	GX-B1306/21-4-23053	2023. 9. 13	所检项目合格	 A photograph showing a person wearing a red hard hat and a light-colored uniform sitting on a red and blue device, possibly a testing or inspection equipment, in a workshop or industrial setting. The person is looking at the device. A timestamp "2023. 8. 23" is visible in the bottom right corner of the image.

60	GX-B1328/20-4-23173	2023. 9. 13	本次共检绝缘手套10只，10只所检项目合格。			
61	GX-B1328/20-4-23174	2023. 9. 13	本次共检绝缘鞋10只，10只所检项目合格。			
62	GX-B1328/20-4-23175	2023. 9. 13	本次共检验电器5支，5支所检项目合格。			

63	GX-B1328/20-4-23176	2023. 9. 13	本次共检短路接地线5套，5套所检项目合格。	 A photograph showing two workers in red hard hats and work clothes performing maintenance on a blue-painted wall structure. One worker is kneeling and using a tool, while the other stands nearby. A yellow bucket and other equipment are on the ground. A timestamp '2023. 9. 13' is visible in the bottom right corner.
64	GX-B1328/20-4-23177	2023. 9. 13	本次共检绝缘杆3只，3只所检项目合格。	 A photograph of a worker in a red hard hat kneeling on a concrete surface. A yellow bucket and a red tool are on the ground. The worker is positioned in front of a blue building. A timestamp '2023. 9. 13' is visible in the bottom right corner.
65	GX-B1322/21-4-23094-23097	2023. 9. 13	本次共检电力电缆4条，4条电力电缆所检项目合格	 A photograph showing two workers in red hard hats inspecting a large, light-colored electrical cabinet. One worker is kneeling and looking into the cabinet, while the other stands behind him. A timestamp '2023/8/31' is visible in the bottom right corner.

66	GX-B1308/21-4-23021	2023. 9. 13	所检项目合格。	
67	GX-B1329/21-4-23133-23135	2023. 9. 14	本次共检氧化锌避雷器3组，3组氧化锌避雷器所检项目合格	
68	GX-B1451/20-4-23116-23121	2023. 9. 14	本次共检高压开关柜6面，6面高压开关柜所检项目合格	

69	GX-B1380/20-4-23012	2023. 9. 14	所检项目合格。	
70	GX-B1328/20-4-23184	2023. 9. 15	本次共检绝缘手套 4只，4只所检项目合格。	
71	GX-B1328/20-4-23185	2023. 9. 15	本次共检绝缘鞋4只， 4只所检项目合格。	

72	GX-B1310/21-4-23145	2023. 9. 15	符合标准要求	
73	GX-B1310/21-4-23146	2023. 9. 15	符合标准要求	
74	GX-B1380/20-4-23013	2023. 9. 15	所检项目合格	

75	GX-B1380/20-4-23014	2023. 9. 15	所检项目合格	
76	GX-B1304/21-4-23003	2023. 9. 15	综合判定：合格。	
77	GX-B1303/21-4-23013	2023. 9. 15	综合判定：合格。	

78	GX-B1382/21-4-23011	2023. 9. 15	所检项目合格。	
----	---------------------	-------------	---------	---