

序号	报告编号	发布日期	结论	影像资料
25	GX-B1424/20-7-23025	2023. 9. 25	依据NB/T 10176-2019单轨吊车所检项目合格。	
26	GX-B1424/20-7-23026	2023. 9. 25	依据NB/T 10176-2019单轨吊车所检项目合格。	
27	GX-B1424/20-7-23027	2023. 9. 25	依据NB/T 10176-2019单轨吊车所检项目合格。	

28	GX-B1424/20-7-23028	2023. 9. 25	依据NB/T 10176-2019单轨吊车所检项目合格。	
29	GX-B1424/20-7-23029	2023. 9. 25	依据NB/T 10176-2019单轨吊车所检项目合格。	
30	GX-B1308/21-7-23016	2023. 9. 19	所检项目合格。	
31	GX-B1499/21-7-23068	2023. 9. 19	所检项目合格。	

32	GX-B1499/21-7-23069	2023. 9. 19	所检项目合格。	 A photograph showing several large blue industrial pumps or motors in a factory or workshop. A person in a red protective suit is visible in the background. A yellow timestamp '2023/05/02' is in the bottom right corner.
33	GX-B1499/21-7-23070	2023. 9. 19	所检项目合格。	 A photograph with a strong purple tint, showing a person in a red protective suit working on machinery. A yellow timestamp '2023/05/02' is in the bottom right corner.
34	GX-B1499/21-7-23071	2023. 9. 19	所检项目合格。	 A photograph with a dark, reddish-purple tint, showing a person in a red protective suit working on machinery. A yellow timestamp '2023/05/02' is in the bottom right corner.