

序号	报告编号	发布日期	结论	影像资料
50	GX-B1495/20-Y-231667-231676	2023年11月7日	本次共检高压开关柜10台，10台高压开关柜检项目合格。	

51	GX-B1495/20-Y-231689-231693	2023年11月7日	本次共检高压开关柜5台，5台高压开关柜检项目合格。	
----	-----------------------------	------------	---------------------------	---

52	GX-B1495/20-Y-231706-231718	2023年11月7日	本次共检高压开关柜13台，13台高压开关柜检项目合格。	
----	-----------------------------	------------	-----------------------------	---

53	GX-B1495/20-Y-231694-231705	2023年11月7日	本次共检高压开关柜12台，12台高压开关柜检项目合格。	
----	-----------------------------	------------	-----------------------------	---

54	GX-B1495/20-Y-231677-231682	2023年11月7日	本次共检高压开关柜6台，6台高压开关柜检项目合。	
----	-----------------------------	------------	--------------------------	---

55	GX-B1495/20-Y-231683-231688	2023年11月7日	本次共检高压开关柜 6台，6台高压开关柜检 项目合格。	
----	-----------------------------	------------	-----------------------------------	---

56	GX-B1329/21-Y-23272~23273	2023年11月7日	本次共检氧化锌避雷器2组，2组氧化锌避雷器所检项目合格。	
----	---------------------------	------------	------------------------------	---

57	GX-B1495/20-Y-231719~ 231733	2023年11月7日	本次共检高压防爆开关 15台，15台高压防爆开 关检项目合格。	
----	---------------------------------	------------	---------------------------------------	---

58	GX-B1423/20-Y-236082	2023年11月8日	综合判定：合格	 A photograph showing a worker wearing a yellow hard hat and a grey jacket, operating a vehicle. The worker is seated in the driver's seat, looking down at the controls. The vehicle is yellow and has a blue and red striped canopy. The background shows a blue sky and a building with traditional Chinese architecture. A yellow timestamp '2023/11/2' is visible in the bottom left corner of the photo.
----	----------------------	------------	---------	---

59	GX-B1423/20-Y-236083	2023年11月8日	综合判定：合格	
----	----------------------	------------	---------	---

60	GX-B1423/20-Y-236084	2023年11月8日	综合判定：合格	
----	----------------------	------------	---------	---

61	GX-B1423/20-Y-236085	2023年11月8日	综合判定：合格	
----	----------------------	------------	---------	---

62	GX-B1328/20-Y-23146	2023年11月8日	本次共检绝缘鞋34只， 34只绝缘鞋所检项目合格。	
----	---------------------	------------	------------------------------	---

63	GX-B1328/20-Y-23147	2023年11月8日	本次共检绝缘手套 34只，34只绝缘手套所 检项目合格。	
----	---------------------	------------	------------------------------------	---

64	GX-B1328/20-Y-23148	2023年11月8日	本次共检验电器9支，9支验电器所检项目合格。 。	
----	---------------------	------------	-----------------------------	---

65	GX-B1328/20-Y-23149	2023年11月8日	本次共检便携式接地和接地短路装置8组，8组便携式接地和接地短路装置所检项目合格。	
----	---------------------	------------	--	---

66	GX-B1328/20-Y-23150	2023年11月8日	所检项目合格。	
----	---------------------	------------	---------	---

67	GX-B1310/21-Y-23146	2023年11月8日	符合标准要求	 A photograph showing a worker in a red safety suit and helmet working on a large, complex industrial component, possibly a turbine or engine part, in a factory setting. The worker is using a tool to inspect or adjust the component. The background shows industrial structures and lighting.
----	---------------------	------------	--------	--

68	GX-B1310/21-Y-23148	2023年11月8日	符合标准要求	 <p data-bbox="1585 699 1697 719">2023/10/21</p>
----	---------------------	------------	--------	---

69	GX-B1428/21-Y-23148	2023年11月8日	无缺陷迹痕显示	
----	---------------------	------------	---------	---

70	GX-B1310/21-Y-23149	2023年11月8日	符合标准要求	
----	---------------------	------------	--------	---

71	GX-B1428/21-Y-23149	2023年11月8日	无缺陷迹痕显示	
----	---------------------	------------	---------	---

72	GX-B1417/22-Y-23101	2023年11月9日	综合判定：合格	
----	---------------------	------------	---------	---

73	GX-B1417/22-Y-23102	2023年11月9日	综合判定：合格	
----	---------------------	------------	---------	---

74	GX-B1531/20-Y-231233~ 231281	2023年11月10日	本次共检隔绝式压缩氧自救器49个，49个隔绝式压缩氧自救器所检项目合格。	
----	---------------------------------	-------------	--------------------------------------	---

75	GX-B1531/20-Y-231282~ 231332	2023年11月10日	本次共检隔绝式压缩氧自救器51个，51个隔绝式压缩氧自救器所检项目合格。	
----	---------------------------------	-------------	--------------------------------------	---

76	GX-B1531/20-Y-231333~ 231382	2023年11月10日	本次共检隔绝式压缩氧自救器50个，50个隔绝式压缩氧自救器所检项目合格。	
----	---------------------------------	-------------	--------------------------------------	---

77	GX-B1531/20-Y-231383~ 231432	2023年11月10日	本次共检隔绝式压缩氧自救器50个，50个隔绝式压缩氧自救器所检项目合格。	
----	---------------------------------	-------------	--------------------------------------	---

78	GX-B1531/20-Y-231433~ 231461	2023年11月10日	本次共检隔绝式压缩氧自救器29个，29个隔绝式压缩氧自救器所检项目合格。	
79	GX-B1306/21-Y-23130	2023年11月13日	除风包设在室内，其余所检项目合格。	

80	GX-B1306/21-Y-23131	2023年11月13日	除风包设在室内外，其余所检项目合格。	
----	---------------------	-------------	--------------------	---