


序号	报告编号	发布日期	结论	影像资料
1	GX-B1502/21-F-23050	2023. 11. 1	I类，容易自燃。	
2	GX-B1501/21-F-23050	2023. 11. 1	煤尘具有爆炸性	
3	GX-B1492/21-F-23024	2023. 11. 7	所检项目合格	 A photograph of a laboratory setting. Two individuals, one wearing a white lab coat and a face mask, are working at a workstation. The workstation is equipped with various pieces of laboratory equipment, including what appears to be a spectrophotometer or similar analytical instrument. There are also some containers and other lab supplies on the counter. A window with yellow curtains is visible in the background. A timestamp '2023/10/30' is visible in the bottom right corner of the image.
4	GX-B1492/21-F-23025	2023. 11. 7	所检项目合格	 A photograph of a laboratory scene. Two people, one in a white lab coat and one in a grey lab coat, are standing at a workstation. The workstation features a large piece of equipment, possibly a furnace or a similar high-temperature instrument, with a control panel and a viewing window. There are also some other lab items on the counter. A timestamp '2023/10/31' is visible in the bottom right corner of the image.

5	GX-B1378/22-F-23240	2023. 11. 7	所检项目合格	 <p>2023/10/31</p>
6	GX-B1378/22-F-23241~F-23242	2023. 11. 7	所检项目合格	 <p>2023/11/1</p>
7	GX-B1489/21-F- 23089	2023. 11. 7	所检项目合格	 <p>2023/10/31</p>

8	GX-B1489/21-F- 23090	2023. 11. 7	所检项目合格	
9	GX-B1600/21-F-23020	2023. 11. 13	可不注水煤层	
10	GX-B1600/21-F-23021	2023. 11. 13	可不注水煤层	
11	GX-B1600/21-F-23022	2023. 11. 13	可不注水煤层	
12	GX-B1502/21-F-23044	2023. 11. 13	II类，自燃。	
13	GX-B1501/21-F-23044	2023. 11. 13	煤尘具有爆炸性	