

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|---------|--|
| 152 | GX-B1522/20-Y-24001 | 2024年2月22日 | 所检项目合格。 |  |
| 153 | GX-B1522/20-Y-24002 | 2024年2月22日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|------------|----------|--|
| 154 | GX-B1306/23-Y-24006 | 2024年2月26日 | 综合判定：合格。 |  |
| 155 | GX-B1306/23-Y-24007 | 2024年2月26日 | 综合判定：合格。 |  |


| | | | | |
|-----|---------------------|------------|----------|---|
| 156 | GX-B1306/23-Y-24008 | 2024年2月26日 | 综合判定：合格。 |  A person wearing a white protective suit and hood is using a tool to inspect a wall in a room. The room contains a white cabinet and a light fixture. A yellow timestamp '2024.1.27' is visible in the bottom left corner of the photo. |
| 157 | GX-B1306/23-Y-24009 | 2024年2月26日 | 综合判定：合格。 |  A person wearing a white protective suit and hood is inspecting a blue door or panel in a room. A yellow timestamp '2024.1.27' is visible in the bottom left corner of the photo. |

| | | | | |
|-----|---------------------|------------|----------|--|
| 158 | GX-B1306/23-Y-24010 | 2024年2月26日 | 综合判定：合格。 |  A photograph showing a worker in a white protective suit and helmet standing next to a blue door in an industrial setting. The worker is holding a tool or device. A yellow timestamp '2024-1-27' is visible in the bottom left corner of the image. |
| 159 | GX-B1306/23-Y-24011 | 2024年2月26日 | 综合判定：合格。 |  A photograph showing a worker in a dark protective suit and hood standing in an industrial area. The worker is holding a device. A window is visible in the background. A yellow timestamp '2024-1-27' is visible in the bottom left corner of the image. |

| | | | | |
|-----|---------------------|------------|----------|--|
| 160 | GX-B1306/23-Y-24012 | 2024年2月26日 | 综合判定：合格。 |  |
| 161 | GX-B1310/21-Y-24001 | 2024年2月28日 | 符合标准要求。 |  |

| | | | | |
|-----|---------------------|------------|---------|--|
| 162 | GX-B1310/21-Y-24002 | 2024年2月28日 | 符合标准要求。 |  |
| 163 | GX-B1310/21-Y-24003 | 2024年2月28日 | 符合标准要求。 |  |

| | | | | |
|-----|---------------------|------------|----------|--|
| 164 | GX-B1310/21-Y-24004 | 2024年2月28日 | 符合标准要求。 |  A worker in a red safety suit and helmet is inspecting a large, circular industrial component. The component has a dark interior with several radial spokes. A yellow timestamp '2024/1/18' is visible in the bottom right corner of the image. |
| 165 | GX-B1428/21-Y-24004 | 2024年2月28日 | 无缺陷迹痕显示。 |  A worker in a red safety suit and helmet is inspecting a large, circular industrial component. The component has a dark interior with several radial spokes. A yellow timestamp '2024/1/18' is visible in the bottom right corner of the image. |

| | | | | |
|-----|---------------------|------------|----------|--|
| 166 | GX-B1310/21-Y-24005 | 2024年2月28日 | 符合标准要求。 |  |
| 167 | GX-B1428/21-Y-24005 | 2024年2月28日 | 无缺陷迹痕显示。 |  |

| | | | | |
|-----|---------------------|------------|---------|---|
| 168 | GX-B1310/21-Y-24006 | 2024年2月28日 | 符合标准要求。 |  <p>A worker wearing a red safety suit and a red helmet is inspecting a large, black, cylindrical object, likely a tire or a component of a vehicle. The worker is positioned on the right side of the frame, looking towards the object. The background shows an industrial setting with various equipment and structures. A yellow timestamp '2024/1/19' is visible in the bottom right corner of the image.</p> |
| 169 | GX-B1557/22-Y-24006 | 2024年2月26日 | 所检项目合格。 |  <p>A yellow CAT bulldozer is parked in a snowy environment. Two people are standing in front of the bulldozer, one on the left and one on the right. The bulldozer has a large blade and is equipped with large, treaded tires. The background shows a clear blue sky and a snow-covered ground. A yellow timestamp '2024/2/19' is visible in the bottom right corner of the image.</p> |

| | | | | |
|-----|---------------------|------------|---------|---|
| 170 | GX-B1557/22-Y-24007 | 2024年2月26日 | 所检项目合格。 |  |
| 171 | GX-B1556/22-Y-24002 | 2024年2月26日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|------------|---------|--|
| 172 | GX-B1556/22-Y-24003 | 2024年2月26日 | 所检项目合格。 |  |
| 173 | GX-B1306/23-Y-24001 | 2024年2月29日 | 综合判定：合格 |  |

| | | | | |
|-----|---------------------|------------|---------|--|
| 174 | GX-B1306/23-Y-24002 | 2024年2月29日 | 综合判定：合格 |  |
| 175 | GX-B1306/23-Y-24003 | 2024年2月29日 | 综合判定：合格 |  |

| | | | | |
|-----|---------------------|------------|---------|---|
| 176 | GX-B1306/23-Y-24004 | 2024年2月29日 | 综合判定：合格 |  A worker in a white uniform is operating a large industrial machine with a control panel. The machine has a red emergency stop button and a digital display. The worker is holding a clipboard and looking at the machine. A yellow timestamp '2024/1/17' is visible in the bottom right corner of the photo. |
| 177 | GX-B1306/23-Y-24005 | 2024年2月29日 | 综合判定：合格 |  A worker in a white uniform is looking at a device in a control room. The worker is holding a small device, possibly a tablet or a handheld terminal. The control room has a large window and a control panel. A yellow timestamp '2024/1/17' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|---------------------|------------|---------|--|
| 178 | GX-B1521/20-Y-24077 | 2024年2月29日 | 所检项目合格。 |  |
| 179 | GX-B1521/20-Y-24078 | 2024年2月29日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|------------|---------|---|
| 180 | GX-B1521/20-Y-24079 | 2024年2月29日 | 所检项目合格。 |  |
| 181 | GX-B1539/22-Y-24029 | 2024年2月28日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|------------|---------|--|
| 182 | GX-B1539/22-Y-24030 | 2024年2月28日 | 所检项目合格。 |  |
| 183 | GX-B1539/22-Y-24031 | 2024年2月28日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|------------|---------|--|
| 184 | GX-B1539/22-Y-24032 | 2024年2月28日 | 所检项目合格。 |  A yellow wheel loader is parked on a dirt surface. Two people are standing in front of it. The loader has 'C105' and 'LUGGON' visible on its side. A yellow date stamp '2024/2/28' is in the bottom right corner of the photo. |
| 185 | GX-B1521/20-Y-24070 | 2024年2月29日 | 所检项目合格。 |  A red tracked loader is parked on a snowy surface. A person is standing in the background. The loader has a large front bucket. A yellow date stamp '2024/2/29' is in the bottom right corner of the photo. |

| | | | | |
|-----|---------------------|------------|---------|--|
| 186 | GX-B1521/20-Y-24071 | 2024年2月29日 | 所检项目合格。 |  |
| 187 | GX-B1521/20-Y-24072 | 2024年2月29日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|------------|---------|--|
| 188 | GX-B1521/20-Y-24073 | 2024年2月29日 | 所检项目合格。 |  |
| 189 | GX-B1521/20-Y-24074 | 2024年2月29日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|------------|---------|--|
| 190 | GX-B1521/20-Y-24075 | 2024年2月29日 | 所检项目合格。 |  |
| 191 | GX-B1521/20-Y-24076 | 2024年2月29日 | 所检项目合格。 |  |