

序号	报告编号	发布日期	结论	影像资料
248	GX-B1363/22-A-24613	2024/11/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
249	GX-B1363/22-A-24614	2024/11/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
250	GX-B1363/22-A-24615	2024/11/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
251	GX-B1363/22-A-24616	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
252	GX-B1363/22-A-24617	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
253	GX-B1363/22-A-24618	2024/11/15	所检项目合格。	 <p>The photograph shows two men in grey work jackets and dark pants inspecting a large, rusted industrial machine. One man is on the left, leaning over the machine, while the other is on the right, looking into the machine's opening. The machine has a yellow warning triangle on its side. In the background, there is a window with a red frame and a green trash bin. A date stamp '2024/11/13' is visible in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
254	GX-B1363/22-A-24619	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
255	GX-B1363/22-A-24620	2024/11/15	所检项目合格。	 <p>The photograph shows two men in light-colored jackets and dark pants inspecting a large, complex industrial machine. The machine has a prominent vertical pipe and a large door. The setting is an indoor workshop or factory floor. A green trash bin is visible on the left, and a window with a red frame is on the right. A date stamp '2024/11/13' is located in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
256	GX-B1363/22-A-24624	2024/11/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
257	GX-B1364/22-A-241246	2024/11/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
258	GX-B1364/22-A-241243	2024/11/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
259	GX-B1364/22-A-241244	2024/11/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
260	GX-B1364/22-A-241245	2024/11/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
261	GX-B1365/20-A-24090	2024/11/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
262	GX-B1365/20-A-24091	2024/11/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
263	GX-B1363/22-A-24602	2024/11/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
264	GX-B1363/22-A-24621	2024/11/18	全厚度拉伸强度为： 1228N/mm，全厚度拉断伸长率为：24%；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
265	GX-B1363/22-A-24629	2024/11/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
266	GX-B1363/22-A-24561	2024/11/18	所检项目合格。	 A photograph showing two men in light blue work jackets inspecting a large, industrial machine. The machine has a prominent vertical pipe on top. One man is wearing yellow gloves and is looking into an open compartment of the machine. The other man is standing to the left, also looking at the machine. The background is a plain wall with a window. A date stamp '2024.11.16' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
267	GX-B1363/22-A-24608	2024/11/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
268	GX-B1363/22-A-24597	2024/11/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
269	GX-B1363/22-A-24622	2024/11/18	所检项目合格。	 A photograph showing two men in white work jackets and yellow gloves inspecting a large, complex industrial machine. The machine has a prominent vertical pipe on top and several compartments. One man is looking into an open compartment while the other stands beside him. The background shows a window and a fan. A date stamp '2024 11 15' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
270	GX-B1509/20-A-24033	2024/11/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
271	GX-B1366/20-A-24120	2024/11/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
272	GX-B1366/20-A-24117	2024/11/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
273	GX-B1366/20-A-24116	2024/11/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1365/20-A-24089	2024/11/18	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
275	GX-B1364/22-A-241304	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
276	GX-B1364/22-A-241307	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
277	GX-B1364/22-A-241306	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
278	GX-B1364/22-A-241305	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
279	GX-B1364/22-A-241310	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1364/22-A-241309	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
281	GX-B1364/22-A-241308	2024/11/15	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
282	GX-B1364/22-A-241311	2024/11/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
283	GX-B1364/22-A-241254	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
284	GX-B1364/22-A-241255	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
285	GX-B1364/22-A-241256	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
286	GX-B1364/22-A-241257	2024/11/19	所检项目合格。	


287	GX-B1364/22-A-241300	2024/11/19	所检项目合格。	
-----	----------------------	------------	---------	--

序号	报告编号	发布日期	结论	影像资料
288	GX-B1364/22-A-241254	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
289	GX-B1364/22-A-241255	2024/11/19	所检项目合格。	 A photograph showing two men in grey work uniforms with a blue logo on the back, inspecting a control panel on a large piece of machinery. The man on the left is wearing glasses. The control panel has a screen and several buttons. The date '2024.11.06' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
290	GX-B1364/22-A-241256	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
291	GX-B1364/22-A-241257	2024/11/19	所检项目合格。	

292	GX-B1364/22-A-241300	2024/11/19	所检项目合格。	
-----	----------------------	------------	---------	--

序号	报告编号	发布日期	结论	影像资料
293	GX-B1364/22-A-241299	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
294	GX-B1364/22-A-241274	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
295	GX-B1364/22-A-241275	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
296	GX-B1364/22-A-241276	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
297	GX-B1364/22-A-241277	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
298	GX-B1364/22-A-241278	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
299	GX-B1364/22-A-241279	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
300	GX-B1364/22-A-241280	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
301	GX-B1364/22-A-241281	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
302	GX-B1364/22-A-241282	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
303	GX-B1364/22-A-241283	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
304	GX-B1364/22-A-241284	2024/11/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
305	GX-B1364/22-A-241285	2024/11/19	所检项目合格。	