







序号	报告编号	发布日期	结论	影像资料
1	GX-B1427/21-6-24109	2025/1/4	符合标准要求	 A photograph showing a worker in a blue uniform and red helmet performing maintenance on a large industrial machine. The worker is wearing a safety harness and is positioned near a large, complex piece of machinery. The date stamp '2024 12 25' is visible in the bottom right corner of the image.
2	GX-B1427/21-6-24110	2025/1/4	符合标准要求	 A photograph showing a worker in a yellow uniform and red helmet standing on a metal platform or walkway. The worker is wearing a safety harness and is positioned near industrial pipes and machinery. The date stamp '2024 12 25' is visible in the bottom right corner of the image.

3	GX-B1427/21-6-24111	2025/1/4	符合标准要求	 <p>2024-12-25</p>
4	GX-B1310/21-6-24405	2025/1/4	符合标准要求	 <p>2024-12-25</p>
5	GX-B1310/21-6-24406	2025/1/4	符合标准要求	 <p>2024-12-25</p>

6	GX-B1310/21-6-24407	2025/1/4	符合标准要求	 <p>2024.12.25</p>	
7	GX-B1310/21-6-24408	2025/1/4	符合标准要求	 <p>2024.12.25</p>	
8	GX-B1310/21-6-24409	2025/1/4	符合标准要求	 <p>2024.12.25</p>	

9	GX-B1310/21-6-24410	2025/1/4	符合标准要求	
10	GX-B1310/21-6-24411	2025/1/4	符合标准要求	
11	GX-B1310/21-6-24412	2025/1/4	符合标准要求	

12	GX-B1310/21-6-24413	2025/1/4	符合标准要求	
13	GX-B1304/21-6-24052	2025/1/6	综合判定合格	
14	GX-B1304/21-6-24053	2025/1/6	综合判定合格	